DNV

INSPECTION REPORT
OF FLAT WEBBING SLING

Report No:
A1824607-03
Date of Inspection:
2 December 2025

Particulars of Owner

Name of Owner:	**M/s. SULZER ROTATING EQUIPMENT SERVICES**
Address of Owner:	**DOHA, STATE OF QATAR**
Place of Inspection:	**DUTEST QATAR**
DNV NPS W/O Number:	**WO# 17462209052**
	A1824607

Scheme of Examination

Type of Inspection: **In-Service Thorough Examination**

As requested by the equipment owner, the undersigned surveyor of this organization, attended their facility to carry out thorough examination of the below item and report the findings as here under:

Particulars of Equipment

Equipment Name and Description:	**Flat Webbing Sling, Duplex polyester flat webbing sling, Both End Soft Eye.**
Manufacturer Name or supplier.:	**DOLEZYCH**
Serial Number:	**DDR06101000020006 & DDR06101000020275**
Quantity:	**02 Nos.**
color:	**Yellow**
Material:	**Polyester**
S.W.L:	**3.0 t**
Width:	**90 mm**
E.W.L:	**4.0 m**
Y.O.M:	**07-2019**
F.O.S:	**7:1**

Additional Equipment Parameters (If Any)

Measuring Tape Sl. N°: VC23-TAG-317, Due Dt.: 04.02.2026

Result of Inspection

The above-mentioned equipment was thoroughly inspected for safe operating conditions. The item was found in satisfactory condition during the time of inspection. The above item was inspected and a report issued as per client requirement.

Previous Examination Details:	**Not Available**
Date of Next Examination:	**2 May 2026**

Authorized Name: ***ROBIN JOHNY***

Authorized Signature:

Surveyor's Name: ***MANOJ MATHEW***

Surveyor's Signature:

DNV 1864 INSPECTION 42 - 158

GL Noble Denton WLL (DNV Qatar), Ghanem Al Thani Business Centre, Office No.: 202, Zone 23, Bin Mahmoud, P.O.Box 22933, Doha, Qatar
Tel: +974 4402 7333 Fax: +974 4466 1969 E-mail: GLNDqatar@dnv.com

© DNV 2014. DNV and the Horizon Graphic are trademarks of DNV AS.