


SAFETYVISION AI

INDUSTRIAL VISUAL SAFETY INSPECTION AUDIT REPORT

Inspection ID: INS-20261006-8FB40E	Date/Time: 2026-10-06 18:11:06
Equipment Type: Industrial Angle Grinder	Model Version: 0.1.0
Operator: QA-Auditor-3	AI Confidence: 88.0%

OVERALL RESULT: REVIEW — AMBIGUOUS / INSUFFICIENT

VISUAL EVIDENCE ARTIFACT



SAFETY COMPONENT VERIFICATION MATRIX

Component	Mandatory	Detection Status	Confidence	Severity	Audit Finding
Protective Wheel Guard	YES	REVIEW	68.0%	MEDIUM	Protective Wheel Guard detection ambiguous or...
Auxiliary Side Handle	YES	REVIEW	72.0%	MEDIUM	Auxiliary Side Handle detection ambiguous or ...
Power Cable & Strain Relief	YES	REVIEW	70.0%	MEDIUM	Power Cable & Strain Relief detection ambiguo...
Safety Trigger / Switch	YES	REVIEW	80.0%	MEDIUM	Safety Trigger / Switch detection ambiguous o...

INSPECTION FINDINGS & REQUIRED ACTION

Root Evaluation: REVIEW — Insufficient or ambiguous visual evidence. Component confidence or visual conditions require verification.

Recommended Action: Perform physical manual inspection by a qualified operator or competent person. Ensure lighting is uniform and retake inspection photograph if necessary.

System Warnings: Protective Wheel Guard detected with marginal confidence (68.0%). | Auxiliary Side Handle detected with marginal confidence (72.0%). | Power Cable & Strain Relief detected with marginal confidence (70.0%). | Safety Trigger / Switch detected with marginal confidence (80.0%).

STATUTORY SAFETY NOTICE & COMPETENT PERSON DISCLAIMER: SafetyVision AI provides automated visual condition verification against configured visual safety criteria only. This software does NOT certify universal, physical, mechanical, or electrical safety and does NOT replace formal statutory inspections, manufacturer safety maintenance, job safety analyses (JSA), or evaluations conducted by an OSHA-defined Competent Person. Unsafe equipment must be tagged out and removed from service immediately.