


SAFETYVISION AI

INDUSTRIAL VISUAL SAFETY INSPECTION AUDIT REPORT

Inspection ID: INS-20261006-F0DCA8	Date/Time: 2026-10-06 21:48:34
Equipment Type: Industrial Angle Grinder	Model Version: 0.1.0
Operator: Factory-QA-Robot	AI Confidence: 99.3%

OVERALL RESULT: PASS — COMPLIANT

VISUAL EVIDENCE ARTIFACT



SAFETY COMPONENT VERIFICATION MATRIX

Component	Mandatory	Detection Status	Confidence	Severity	Audit Finding
Protective Wheel Guard	YES	PASS	97.4%	NONE	Protective Wheel Guard verified in position.
Auxiliary Side Handle	YES	PASS	98.6%	NONE	Auxiliary Side Handle verified in position.
Power Cable & Strain Relief	YES	PASS	98.6%	NONE	Power Cable & Strain Relief verified in posit...
Safety Trigger / Switch	YES	PASS	98.1%	NONE	Safety Trigger / Switch verified in position.

INSPECTION FINDINGS & REQUIRED ACTION

Root Evaluation: PASS — All mandatory safety components detected and spatially verified on Industrial Angle Grinder.

Recommended Action: Equipment satisfies configured visual safety requirements. Proceed with standard operational workflow.

STATUTORY SAFETY NOTICE & COMPETENT PERSON DISCLAIMER: SafetyVision AI provides automated visual condition verification against configured visual safety criteria only. This software does NOT certify universal, physical, mechanical, or electrical safety and does NOT replace formal

statutory inspections, manufacturer safety maintenance, job safety analyses (JSA), or evaluations conducted by an OSHA-defined Competent Person. Unsafe equipment must be tagged out and removed from service immediately.