

SAFETYVISION AI

INDUSTRIAL VISUAL SAFETY INSPECTION AUDIT REPORT

Inspection ID: INS-20261007-4E10B8	Date/Time: 2026-10-07 07:17:30
Equipment Type: Industrial Angle Grinder	Model Version: 0.1.0
Operator: Tech-104	AI Confidence: 0.0%

OVERALL RESULT: REVIEW — AMBIGUOUS / INSUFFICIENT

VISUAL EVIDENCE ARTIFACT



SAFETY COMPONENT VERIFICATION MATRIX

Component	Mandatory	Detection Status	Confidence	Severity	Audit Finding
-----------	-----------	------------------	------------	----------	---------------

INSPECTION FINDINGS & REQUIRED ACTION

Root Evaluation: REVIEW — Target equipment could not be identified with adequate confidence.

Recommended Action: Re-align camera framing, verify lighting, and ensure equipment is fully in view.

System Warnings: Insufficient visual evidence or equipment absent.

STATUTORY SAFETY NOTICE & COMPETENT PERSON DISCLAIMER: SafetyVision AI provides automated visual condition verification against configured visual safety criteria only. This software does NOT certify universal, physical, mechanical, or electrical safety and does NOT replace formal statutory inspections, manufacturer safety maintenance, job safety analyses (JSA), or evaluations conducted by an OSHA-defined Competent Person. Unsafe equipment must be tagged out and removed from service immediately.