

SAFETYVISION AI

INDUSTRIAL VISUAL SAFETY INSPECTION AUDIT REPORT

Inspection ID: TEST-INS-001	Date/Time: 2026-10-07 03:38:58
Equipment Type: Industrial Angle Grinder	Model Version: 0.1.0
Operator: Test Auditor	AI Confidence: 96.5%

OVERALL RESULT: FAIL — CRITICAL VIOLATION

SAFETY COMPONENT VERIFICATION MATRIX

Component	Mandatory	Detection Status	Confidence	Severity	Audit Finding
Protective Wheel Guard	YES	FAIL	N/A	CRITICAL	Abrasive wheel guard is missing. Operating wi...
Auxiliary Side Handle	YES	PASS	94.0%	NONE	Handle verified in position.

INSPECTION FINDINGS & REQUIRED ACTION

Root Evaluation: FAIL — Missing mandatory components: guard.
Recommended Action: Lockout tool immediately and schedule competent-person inspection.

STATUTORY SAFETY NOTICE & COMPETENT PERSON DISCLAIMER: SafetyVision AI provides automated visual condition verification against configured visual safety criteria only. This software does NOT certify universal, physical, mechanical, or electrical safety and does NOT replace formal statutory inspections, manufacturer safety maintenance, job safety analyses (JSA), or evaluations conducted by an OSHA-defined Competent Person. Unsafe equipment must be tagged out and removed from service immediately.