

GEICO

01

Claim #: 0477934980101013-01
Workfile ID: 2f19896a

Supplement of Record 1 Summary

Written By: MATTHEW ADAMS, 1/28/2021 9:06:05 AM
Adjuster: A707

Insured:	Aric Dama	Owner Policy #:	4452756838	Claim #:	0477934980101013-01
Type of Loss:	Collision	Date of Loss:	10/27/2020 01:42 PM	Days to Repair:	4
Point of Impact:	07 Left Rear	Deductible:	2000.00		

Owner (Insured):	Inspection Location:	Repair Facility:
Aric Dama	360 Collision Center	MOPPART AUTO COLLISION SWEDESBORO
2031 Chestnut St	360 Collision Center	2191 RT 322
Philadelphia, PA 19103	3410 TULIP ST	SWEDESBORO, NJ 08085
(630) 624-5908 Evening	PHILADELPHIA, PA 19134	473523000 Federal ID
(630) 624-5908 Cellular	Drive-in	02725A License Number
	(215) 331-1267 Day	

VEHICLE

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

VIN:	5YJ3E1EB0JF171039	Production Date:		Interior Color:	
License:	LGV8288	Odometer:	17294	Exterior Color:	BLACK
State:	PA	Condition:			

TRANSMISSION	STEERING WHEEL TOUCH CONTROLS	STEREO	ANTI-LOCK BRAKES (4)
AUTOMATIC TRANSMISSION	CONSOLE/STORAGE	SEARCH/SEEK	GLASS & MIRRORS
4 WHEEL DRIVE	HOME LINK	AUXILIARY AUDIO CONNECTION	DUAL MIRRORS
DRIVER CONVENIENCE	INSTRUMENT PANEL	ROOF	TINTED GLASS
KEYLESS ENTRY	TRACTION CONTROL	SKYVIEW ROOF	SEATS
MESSAGE CENTER	STABILITY CONTROL	SAFETY	LEATHER SEATS
MEMORY PACKAGE	BLIND SPOT DETECTION	DRIVERS SIDE AIR BAG	BUCKET SEATS
POWER DRIVER SEAT	LANE DEPARTURE WARNING	PASSENGER AIR BAG	POWER PASSENGER SEAT
POWER WINDOWS	AIR CONDITIONING	FRONT SIDE IMPACT AIR BAGS	HEATED SEATS
POWER LOCKS	CLIMATE CONTROL	HEAD/CURTAIN AIR BAGS	REAR HEATED SEATS
POWER MIRRORS	REAR DEFOGGER	PAINT	REAR END
HEATED MIRRORS	HANDS FREE DEVICE	CLEARCOAT PAINT	PARKING SENSORS
POWER TRUNK/LIFTGATE	WOOD INTERIOR TRIM	FRONT END	BACKUP CAMERA
CRUISE CONTROL	NAVIGATION SYSTEM	FOG LAMPS	WHEELS
INTERMITTENT WIPERS	RADIO	XENON OR L.E.D. HEADLAMPS	4-WHEEL DISC BRAKES
TILT WHEEL	AM RADIO	POWER STEERING	FULL WHEEL COVERS
TELESCOPIC WHEEL	FM RADIO	POWER BRAKES	

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		INFORMATION LABELS					
2	*	S01 Repl Tire info label	101393500C	1	<u>24.99</u>	0.2	
3		HOOD					
4		S01 R&I Storage compart	108167488D			1.2	
5		S01 R&I Mat	109085300C			Incl.	
6		S01 R&I Weatherstrip	109049200B			0.3	
7		WHEELS					
8		S01 Repl LT/Rear Wheel, alloy 20x8.5 ET 35 SPORT	123422700D	1	750.00 m	0.3	
		NOTE: SCRAPED, WRONG SIZE PUT ON ORIGINAL ESTIMATE LABOR: Add for balance and weights.					
9		PILLARS, ROCKER & FLOOR					
10		S01 Blnd LT Uniside assy	1073673S0A		s		4.0
11		S01 R&I LT Applique	110925375D			0.3	
12		S01 R&I LT Rocker molding	108982800C			0.6	
13		S01 R&I LT W'strip on body front door	109049900C			0.4	
14		S01 R&I LT W'strip on body rear door	109051100D			0.4	
15		S01 R&I LT Applique cap	110008700C			0.2	
16		S01 Repl LT Insert	109084400C	1	28.00	0.1	
17		FRONT DOOR					
18		S01 R&I LT R&I door assy	1081421E0C			1.1	
19		S01 R&I LT R&I trim panel	109040901D			0.5	
20		REAR DOOR					
21	*	S01 Rpr LT Outer panel	1081459S0A			<u>0.5</u>	<u>1.8</u>
		NOTE: PAINT CRACKED WITH SMALL DENT, BLEND WITHIN PANEL					
22		S01	Add for Clear Coat				0.7
23		S01	Add for Edging				0.5
24		S01 R&I LT Belt molding	108074500B			0.2	
25		S01 R&I LT Door glass TESLA	107790400A			0.5	
26		S01 R&I LT Handle, outside	108183100D			0.4	
		NOTE: LABOR: Time is after door glass and regulator are removed.					
27		S01 R&I LT Regulator module	109662200F			0.5	
28		S01 R&I LT R&I trim panel	109041301D			0.5	
29		S01 R&I LT Striker	110726200C			0.2	
30		QUARTER PANEL					
31	*	S01 Rpr LT Quarter panel	1073677S0A		s	<u>8.5</u>	<u>2.3</u>
		NOTE: DENTED LOWER NEAR BUMPER					
32		S01	Overlap Major Adj. Panel				-0.4
33			Add for Clear Coat				0.4
34		R&I	LT Splash shield	108158300B		0.3	
35	#	Blnd	LT ROCKER PANEL				0.5
36		S01 Repl	LT Pressure vent	109875100C	1	11.00	0.2

Supplement of Record 1 Summary

2018 TESLA Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

37		S01	R&I	LT Qtr glass TESLA	109875700F				1.3	
38	*	S01	Rpr	LT Floor extn	1104199S0A				<u>1.0</u>	<u>0.5</u>
NOTE: BUCKLED										
39	REAR BODY & FLOOR									
40	*	S01	Rpr	LT Lower extn	SEE FOOTNOTE				<u>3.0</u>	<u>1.0</u>
NOTE: BUCKLED AND DENTED										
41		S01	R&I	LT Side trim	108293200I				0.1	
42	REAR LAMPS									
43			R&I	LT Tail lamp assy	107739700G				0.3	
44	REAR BUMPER									
45				O/H bumper assy	NONE				2.5	
46			R&I	R&I bumper cover	1108905S0A				Incl.	
47	*	<>	S01	Rpr	Bumper cover	1108905S0A			<u>3.0</u>	<u>2.7</u>
NOTE: SCRAPED LT SIDE										
48				Overlap Major Non-Adj. Panel						-0.2
49	*			Add for Clear Coat						<u>1.2</u>
50			Repl	Add for park sensor		1		m	0.4	
51	VEHICLE DIAGNOSTICS									
52	*	S01	Repl	Pre-repair scan		1		m	<u>1.0</u>	
NOTE: ADDITIONAL TIME GIVEN DUE TO TESLA TOOLBOX SET UP										
53	*	S01	Repl	Post-repair scan		1		m	<u>1.0</u>	
54	MISCELLANEOUS OPERATIONS									
55	#	S01	Repl	Cover Car Complete		1	5.00			0.2
56	#			Hazardous Waste Disposal		1	3.00	T		
57	#		Repl	Restore Corrosion Protection		1	10.00		0.2	
58	#	S01	Subl	Mount and Balance		1	15.00			
59	#	S01	Repl	VIN LABEL		1	149.99		0.1	
60	#	S01	Repl	COVER INTERIOR FOR REPAIRS		1	5.00		0.2	
61	#	S01	Repl	Color sand and Buff Adjustment		1			1.0	
62	#	S01		RESET ELECTRICAL COMPONENTS		1			1.0	
63	#	S01	Repl	Flex Additive adj		1	10.00	T		
64	#	S01	Repl	Urethane Glass Kit		1	15.00	T		
65	#	S01	Rpr	D&R Battery					0.2	
66	#	S01		POWER DOWN HV SYSTEM		1			1.0	
67	#	S01		POWER UP HV SYSTEM		1			1.0	
68	#	S01	Repl	CHARGING DOOR COVER		1	1.00			
69	#	S01		ADJUSTMENT FOR AP		1	1,178.10			
NOTE: LABOR RATE ADJUSTMENT SEE CLAIM SUMMARY										
70	#	S01		ADJUSTMENT FOR AP		1	349.60			
NOTE: PAINT LABOR SEE CLAIM SUMMARY										
71	#	S01		ADJUSTMENT FOR AP		1	121.60			
NOTE: PAINT MATERIALS SEE CLAIM SUMMARY										
72	#	S01		ADJUSTMENT FOR AP		1	-79.90			

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

NOTE: ADJUSTMENT FOR NJ TAX

	SUBTOTALS	2,597.38	35.7	15.2
--	-----------	----------	------	------

NOTES

Estimate Notes:

Copy of Estimate was furnished to the owner of the vehicle. Owner has not chosen repair shop at time of estimate

Prior Damage Notes:

NO PRIOR DAMAGE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,569.38
Body Labor	35.7 hrs @	\$ 52.00 /hr	1,856.40
Paint Labor	15.2 hrs @	\$ 52.00 /hr	790.40
Paint Supplies	15.2 hrs @	\$ 32.00 /hr	486.40
Miscellaneous			28.00
Subtotal			5,730.58
Sales Tax	\$ 5,730.58 @	8.0000 %	458.45
Total Cost of Repairs			6,189.03
Deductible			2,000.00
Total Adjustments			2,000.00
Net Cost of Repairs			4,189.03

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Changed Items							
6	*	Rpr	LT Quarter panel	1073677S0A	s	-2.5	-2.3
			NOTE: DENTED LOWER NEAR BUMPER				
31	*	S01 Rpr	LT Quarter panel	1073677S0A	s	8.5	2.3
			NOTE: DENTED LOWER NEAR BUMPER				
7	*		Add for Clear Coat				-1.1
33		S01	Add for Clear Coat				0.4
15	* <>	Rpr	Bumper cover	1108905S0A		-3.0	-2.5
			NOTE: SCRAPED LT SIDE				
47	* <>	S01 Rpr	Bumper cover	1108905S0A		3.0	2.7
			NOTE: SCRAPED LT SIDE				
20	#	Repl	Cover Car Complete	1			-0.2
55	#	S01 Repl	Cover Car Complete	1	5.00		0.2
Deleted Items							
1	#		Electronic Signature for Andrew Dages; PA License #678972	1			
2	WHEELS						
3	**	Repl	RECOND LT/Rear Wheel, alloy 18x8.5" "PINWHEEL" +25%	123422101A	1	-156.25 m	-0.3
			NOTE: WHEELS OF AMERICA (610) 586-4590				
4	#	Subl	Suspension Alignment	1	-79.95 T		
5	#		Wheel balance	1	-7.50 T		
22	#		Flex Additive	1	-6.00 T		
Added Items							
1	INFORMATION LABELS						
2	*	S01 Repl	Tire info label	101393500C	1	24.99	0.2
3	HOOD						
4		S01 R&I	Storage compart	108167488D			1.2
5		S01 R&I	Mat	109085300C			Incl.
6		S01 R&I	Weatherstrip	109049200B			0.3
7	WHEELS						
8		S01 Repl	LT/Rear Wheel, alloy 20x8.5 ET 35 SPORT	123422700D	1	750.00 m	0.3
			NOTE: SCRAPED, WRONG SIZE PUT ON ORIGINAL ESTIMATE				
			LABOR: Add for balance and weights.				
9	PILLARS, ROCKER & FLOOR						
10		S01 Blnd	LT Uniside assy	1073673S0A	s		4.0
11		S01 R&I	LT Applique	110925375D		0.3	
12		S01 R&I	LT Rocker molding	108982800C		0.6	
13		S01 R&I	LT W'strip on body front door	109049900C		0.4	
14		S01 R&I	LT W'strip on body rear door	109051100D		0.4	

Supplement of Record 1 Summary

2018 TESLA Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

15		S01	R&I	LT Applique cap	110008700C				0.2	
16		S01	Repl	LT Insert	109084400C	1	28.00		0.1	
17	FRONT DOOR									
18		S01	R&I	LT R&I door assy	1081421E0C				1.1	
19		S01	R&I	LT R&I trim panel	109040901D				0.5	
20	REAR DOOR									
21	*	S01	Rpr	LT Outer panel	1081459S0A				<u>0.5</u>	<u>1.8</u>
				NOTE: PAINT CRACKED WITH SMALL DENT, BLEND WITHIN PANEL						
22		S01		Add for Clear Coat						0.7
23		S01		Add for Edging						0.5
24		S01	R&I	LT Belt molding	108074500B				0.2	
25		S01	R&I	LT Door glass TESLA	107790400A				0.5	
26		S01	R&I	LT Handle, outside	108183100D				0.4	
				NOTE: LABOR: Time is after door glass and regulator are removed.						
27		S01	R&I	LT Regulator module	109662200F				0.5	
28		S01	R&I	LT R&I trim panel	109041301D				0.5	
29		S01	R&I	LT Striker	110726200C				0.2	
32		S01		Overlap Major Adj. Panel						-0.4
36		S01	Repl	LT Pressure vent	109875100C	1	11.00		0.2	
37		S01	R&I	LT Qtr glass TESLA	109875700F				1.3	
38	*	S01	Rpr	LT Floor extn	1104199S0A				<u>1.0</u>	<u>0.5</u>
				NOTE: BUCKLED						
39	REAR BODY & FLOOR									
40	*	S01	Rpr	LT Lower extn	SEE FOOTNOTE				<u>3.0</u>	<u>1.0</u>
				NOTE: BUCKLED AND DENTED						
41		S01	R&I	LT Side trim	108293200I				0.1	
51	VEHICLE DIAGNOSTICS									
52	*	S01	Repl	Pre-repair scan		1		m	<u>1.0</u>	
				NOTE: ADDITIONAL TIME GIVEN DUE TO TESLA TOOLBOX SET UP						
53	*	S01	Repl	Post-repair scan		1		m	<u>1.0</u>	
58	#	S01	Subl	Mount and Balance		1	15.00			
59	#	S01	Repl	VIN LABEL		1	149.99		0.1	
60	#	S01	Repl	COVER INTERIOR FOR REPAIRS		1	5.00		0.2	
61	#	S01	Repl	Color sand and Buff Adjustment		1			1.0	
62	#	S01		RESET ELECTRICAL COMPONENTS		1			1.0	
63	#	S01	Repl	Flex Additive adj		1	10.00	T		
64	#	S01	Repl	Urethane Glass Kit		1	15.00	T		
65	#	S01	Rpr	D&R Battery					0.2	
66	#	S01		POWER DOWN HV SYSTEM		1			1.0	
67	#	S01		POWER UP HV SYSTEM		1			1.0	
68	#	S01	Repl	CHARGING DOOR COVER		1	1.00			
69	#	S01		ADJUSTMENT FOR AP		1	1,178.10			
				NOTE: LABOR RATE ADJUSTMENT SEE CLAIM SUMMARY						

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

70	#	S01	ADJUSTMENT FOR AP NOTE: PAINT LABOR SEE CLAIM SUMMARY	1	349.60		
71	#	S01	ADJUSTMENT FOR AP NOTE: PAINT MATERIALS SEE CLAIM SUMMARY	1	121.60		
72	#	S01	ADJUSTMENT FOR AP NOTE: ADJUSTMENT FOR NJ TAX	1	-79.90		
SUBTOTALS					2,334.68	26.2	7.6

NOTES

Estimate Notes:

Copy of Estimate was furnished to the owner of the vehicle. Owner has not chosen repair shop at time of estimate

Prior Damage Notes:

NO PRIOR DAMAGE

TOTALS SUMMARY

Category	Basis		Rate	Cost \$
Parts				2,403.13
Body Labor	26.2 hrs	@	\$ 52.00 /hr	1,362.40
Paint Labor	7.6 hrs	@	\$ 52.00 /hr	395.20
Paint Supplies	7.6 hrs	@	\$ 32.00 /hr	243.20
Miscellaneous				-68.45
Subtotal				4,335.48
Sales Tax	\$ 4,335.48	@	8.0000 %	346.84
Total Supplement Amount				4,682.32
NET COST OF SUPPLEMENT				4,682.32

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	1,506.71	ANDREW DAGES
Supplement S01	4,682.32	MATTHEW ADAMS
Workfile Total:	\$ 6,189.03	
TOTAL ADJUSTMENTS:	\$ 2,000.00	
NET COST OF REPAIRS:	\$ 4,189.03	

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD ANY INSURANCE COMPANY OR OTHER PERSON FILES AN APPLICATION FOR INSURANCE OR STATEMENT OF CLAIM CONTAINING ANY MATERIALLY FALSE INFORMATION OR CONCEALS FOR THE PURPOSE OF MISLEADING, INFORMATION CONCERNING ANY FACT MATERIAL THERETO COMMITS A FRAUDULENT INSURANCE ACT, WHICH IS A CRIME AND SUBJECTS THE PERSON TO CRIMINAL AND CIVIL PENALTIES.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED: D=DISCONTINUED PART A=APPROXIMATE PRICE B=BODY LABOR D=DIAGNOSTIC E=ELECTRICAL F=FRAME G=GLASS M=MECHANICAL P=PAINT LABOR S=STRUCTURAL T=TAXED MISCELLANEOUS X=NON TAXED MISCELLANEOUS ADJ=ADJACENT ALGN=ALIGN A/M=AFTERMARKET BLND=BLEND CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION D&R=DISCONNECT AND RECONNECT EST=ESTIMATE EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY INCL=INCLUDED MISC=MISCELLANEOUS NON-ADJ=NON ADJACENT O/H=OVERHAUL OP=OPERATION NO=LINE NUMBER QTY=QUANTITY RECOND=RECONDITION REFN=REFINISH REPL=REPLACE R&I=REMOVE AND INSTALL R&R=REMOVE AND REPLACE RPR=REPAIR RT=RIGHT SECT=SECTION SUBL=SUBLET LT=LEFT W/O=WITHOUT W/_=WITH/_ #=MANUAL LINE ENTRY *=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED]. **=DATABASE LINE WITH AFTERMARKET N=NOTES ATTACHED TO LINE NAGS=NATIONAL AUTO GLASS SPECIFICATIONS. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

THE ATTACHED ESTIMATE REPRESENTS AN APPRAISAL OF THE COST OF REPAIR FOR THE VISIBLE DAMAGE TO THE VEHICLE NOTED AT THE TIME OF INSPECTION NECESSARY TO RETURN THE VEHICLE TO ITS PREDAMAGED CONDITION. COSTS ABOVE THE APPRAISED AMOUNT MAY BE THE RESPONSIBILITY OF THE VEHICLE OWNER. THERE IS NO REQUIREMENT THAT THE VEHICLE OWNER USE ANY SPECIFIED REPAIR SHOP. INFORMATION REGARDING REPAIR FACILITIES WHICH WILL BE ABLE TO REPAIR THE VEHICLE FOR THE APPRAISED AMOUNT IS AVAILABLE FROM THE INSURANCE COMPANY. IF USED PARTS ARE SPECIFIED, THEY ARE REQUIRED TO BE OF LIKE KIND AND QUALITY TO THOSE BEING REPLACED. INCIDENTAL CHARGES SUCH AS TOWING, PROTECTIVE CARE, CUSTODY, STORAGE, DEPRECIATION, BATTERY AND TIRE REPLACEMENT ARE NOTED WHEN APPLICABLE.

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR7QA18, CCC Data Date 01/18/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.
X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.
CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel.
HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non
Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace.
R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel.
Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway
Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Supplement of Record 1 Summary

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

In accordance with Pennsylvania statute (63 P.S. Section 861(c)), the appraiser may use photographs, videos, and telephone calls to prepare a repair estimate. The submission of photos or videos is NOT REQUIRED to obtain a repair estimate. Additionally, supplemental repair estimates may be completed through the use of photographs, videos, or telephonic means unless the repairs are disputed.