### **GFICO**

GEICO Delaware License #1366439 For supplement requests copy the link below partners.geico.com

5260 Western Ave Chevy Chase, MD 20815

Phone: (215) 896-7389 Fax: (866) 328-0246

Claim #: Workfile ID:

0477934980101013-01

2f19896a

### Estimate of Record

Written By: ANDREW DAGES, License Number: 1366439, 11/24/2020 4:58:37 PM

Adjuster: A707

Insured: Aric Dama Owner Policy #: 4452756838 Claim #: 0477934980101013-01

Collision Date of Loss: 10/27/2020 01:42 PM Days to Repair: Type of Loss:

Point of Impact: 07 Left Rear Deductible: 2000.00

Owner (Insured): Inspection Location: Appraiser Information: Repair Facility:

Aric Dama 360 Collision Center 2031 Chestnut St 360 Collision Center Philadelphia, PA 19103 3410 TULIP ST

(630) 624-5908 Evening PHILADELPHIA, PA 19134

(630) 624-5908 Cellular Drive-in

(215) 331-1267 Day

ADAGES@GEICO.COM OWNER'S CHOICE

#### **VEHICLE**

(215) 896-7389

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

VIN: 5YJ3E1EB0JF171039 Production Date: Interior Color:

License: LGV8288 Odometer: 17294 Exterior Color: **BLACK** 

State: PΑ Condition:

TRANSMISSION STEERING WHEEL TOUCH STEREO ANTI-LOCK BRAKES (4)

CONTROLS

AUTOMATIC TRANSMISSION CONSOLE/STORAGE GLASS & MIRRORS SEARCH/SEEK 4 WHEEL DRIVE HOME LINK **AUXILIARY AUDIO CONNECTION DUAL MIRRORS** DRIVER CONVENIENCE **INSTRUMENT PANEL ROOF TINTED GLASS** 

**KEYLESS ENTRY** TRACTION CONTROL SKYVIEW ROOF **SEATS** 

MESSAGE CENTER STABILITY CONTROL **SAFETY** LEATHER SEATS MEMORY PACKAGE **BLIND SPOT DETECTION** DRIVERS SIDE AIR BAG **BUCKET SEATS** 

POWER DRIVER SEAT LANE DEPARTURE WARNING PASSENGER AIR BAG POWER PASSENGER SEAT

**POWER WINDOWS** AIR CONDITIONING FRONT SIDE IMPACT AIR BAGS **HEATED SEATS** POWER LOCKS CLIMATE CONTROL HEAD/CURTAIN AIR BAGS REAR HEATED SEATS

**POWER MIRRORS** PAINT REAR DEFOGGER **REAR END HEATED MIRRORS** HANDS FREE DEVICE CLEARCOAT PAINT PARKING SENSORS POWER TRUNK/LIFTGATE WOOD INTERIOR TRIM FRONT END **BACKUP CAMERA** 

CRUISE CONTROL **NAVIGATION SYSTEM** FOG LAMPS WHEELS

4-WHEEL DISC BRAKES INTERMITTENT WIPERS **RADIO** XENON OR L.E.D. HEADLAMPS

0477934980101013-01

Workfile ID:

2f19896a

# Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

TILT WHEEL AM RADIO POWER STEERING TELESCOPIC WHEEL FM RADIO POWER BRAKES

FULL WHEEL COVERS

# Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#		Electronic Signature for Andrew Dages; PA License #678972		1			
2	WHEELS							
3	**	Repl	RECOND LT/Rear Wheel, alloy 18x8.5" "PINWHEEL" +25%	123422101A	1	<u>156.25</u> m	0.3	
			NOTE: WHEELS OF AMERICA (610) 586	6-4590				
4	#	Subl	Suspension Alignment		1	79.95 T		
5	#		Wheel balance		1	7.50 T		
6	QUARTER PA	NEL						
7	*	Rpr	LT Quarter panel	1073677S0A		S	<u>2.5</u>	2.3
			NOTE: DENTED LOWER NEAR BUMPER	?				
8	*		Add for Clear Coat					<u>1.1</u>
9		R&I	LT Splash shield	108158300B			0.3	
10	#	Blnd	LT ROCKER PANEL					0.5
11	REAR LAMPS							
12		R&I	LT Tail lamp assy	107739700G			0.3	
13	REAR BUMPE	:R						
14			O/H bumper assy	NONE			2.5	
15		R&I	R&I bumper cover	1108905S0A			Incl.	
16	* <>	Rpr	Bumper cover	1108905S0A			<u>3.0</u>	<u>2.5</u>
			NOTE: SCRAPED LT SIDE					
17			Overlap Major Non-Adj. Panel					-0.2
18	*		Add for Clear Coat					<u>1.2</u>
19		Repl	Add for park sensor		1	m	0.4	
20	MISCELLANE	OUS OF	PERATIONS					
21	#	Repl	Cover Car Complete		1			0.2
22	#		Flex Additive		1	6.00 T		
23	#		Hazardous Waste Disposal		1	3.00 T		
24	#	Repl	Restore Corrosion Protection		1	10.00	0.2	
				SUBTOTALS		262.70	9.5	7.6

# **NOTES**

Estimate Notes:

Copy of Estimate was furnished to the owner of the vehicle. Owner has not chosen repair shop at time of estimate

Prior Damage Notes:

NO PRIOR DAMAGE

0477934980101013-01

Workfile ID: 2f19896a

### Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

### **ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$	
Parts	,			166.25
Body Labor	9.5 hrs	@	\$ 52.00 /hr	494.00
Paint Labor	7.6 hrs	@	\$ 52.00 /hr	395.20
Paint Supplies	7.6 hrs	@	\$ 32.00 /hr	243.20
Miscellaneous				96.45
Subtotal				1,395.10
Sales Tax	\$ 1,395.10	@	8.0000 %	111.61
Total Cost of Repairs				1,506.71
Deductible				2,000.00
Total Adjustments				2,000.00
Net Cost of Repairs				-493.29

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

## ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

- \*\*\*IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:
- \*\*\*\*OWNER LIMITED GUARANTEE\*\*\*\* WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

0477934980101013-01

2f19896a

Workfile ID:

#### Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD ANY INSURANCE COMPANY OR OTHER PERSON FILES AN APPLICATION FOR INSURANCE OR STATEMENT OF CLAIM CONTAINING ANY MATERIALLY FALSE INFORMATION OR CONCEALS FOR THE PURPOSE OF MISLEADING, INFORMATION CONCERNING ANY FACT MATERIAL THERETO COMMITS A FRAUDULENT INSURANCE ACT, WHICH IS A CRIME AND SUBJECTS THE PERSON TO CRIMINAL AND CIVIL PENALTIES.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED:D=DISCONTINUED PART A=APPROXIMATE PRICE B=BODY LABOR D=DIAGNOSTIC E=ELECTRICAL F=FRAME G=GLASS M=MECHANICAL P=PAINT LABOR S=STRUCTURAL T=TAXED MISCELLANEOUS X=NON TAXED MISCELLANEOUS ADJ=ADJACENT ALGN=ALIGN A/M=AFTERMARKET BLND=BLEND CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION D&R=DISCONNECT AND RECONNECT EST=ESTIMATE EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY INCL=INCLUDED MISC=MISCELLANEOUS NON-ADJ=NON ADJACENT O/H=OVERHAUL OP=OPERATION NO=LINE NUMBER QTY=QUANTITY RECOND=RECONDITION REFN=REFINISH REPL=REPLACE R&I=REMOVE AND INSTALL R&R=REMOVE AND REPLACE RPR=REPAIR RT=RIGHT SECT=SECTION SUBL=SUBLET LT=LEFT W/O=WITHOUT W/\_=WITH/\_ #=MANUAL LINE ENTRY \*=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED]. \*\*=DATABASE LINE WITH AFTERMARKET N=NOTES ATTACHED TO LINE NAGS=NATIONAL AUTO GLASS SPECIFICATIONS. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

THE ATTACHED ESTIMATE REPRESENTS AN APPRAISAL OF THE COST OF REPAIR FOR THE VISIBLE DAMAGE TO THE VEHICLE NOTED AT THE TIME OF INSPECTION NECESSARY TO RETURN THE VEHICLE TO ITS PREDAMAGED CONDITION. COSTS ABOVE THE APPRAISED AMOUNT MAY BE THE RESPONSIBILITY OF THE VEHICLE OWNER. THERE IS NO REQUIREMENT THAT THE VEHICLE OWNER USE ANY SPECIFIED REPAIR SHOP. INFORMATION REGARDING REPAIR FACILITIES WHICH WILL BE ABLE TO REPAIR THE VEHICLE FOR THE APPRAISED AMOUNT IS AVAILABLE FROM THE INSURANCE COMPANY. IF USED PARTS ARE SPECIFIED, THEY ARE REQUIRED TO BE OF LIKE KIND AND QUALITY TO THOSE BEING REPLACED. INCIDENTAL CHARGES SUCH AS TOWING, PROTECTIVE CARE, CUSTODY, STORAGE, DEPRECIATION, BATTERY AND TIRE REPLACEMENT ARE NOTED WHEN APPLICABLE.

Claim #: Workfile ID: 0477934980101013-01

2f19896a

# Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR7QA18, CCC Data Date 11/13/2020, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

0477934980101013-01

Workfile ID:

2f19896a

### Estimate of Record

2018 TESL Model 3 AWD w/Long Range Battery 4D SED Electric- Electric BLACK

In accordance with Pennsylvania statute (63 P.S. Section 861(c)), the appraiser may use photographs, videos, and telephone calls to prepare a repair estimate. The submission of photos or videos is NOT REQUIRED to obtain a repair estimate. Additionally, supplemental repair estimates may be completed through the use of photographs, videos, or telephonic means unless the repairs are disputed.