



CONDITION BASED ASSESSMENT

FULL SCANNING REPORT

SBUM DIAGNOSTIC PAHANG

TNB BAHAGIAN PEMBAHAGIAN PAHANG

FUNCTIONAL LOCATION (ERMS)	:	CCHL/PCE/J00155
FUNCTIONAL LOCATION (SITE)	:	CCHL/PCE/J00155
SUBSTATION NAME (ERMS)	:	S/S LOJI AIR HABU
SUBSTATION NAME (SITE)	:	SS LOJI AIR HABU
COORDINATE	:	4.438017, 101.390712
SUBSTATION TYPE	:	SS
AREA	:	CAMERON HIGHLAND
STATE	:	PAHANG
PO	:	42289580
DATE	:	01 JUN 2026

SCANNED BY	
THERMOGRAPHY	: MUHAMMAD ADAM BIN SAFARUDDIN (2017MY34N004)
ULTRASOUND	: MUHAMMAD ADAM BIN SAFARUDDIN (UET2016316)

EQUIPMENT/TOOLS	
THERMOGRAPHY	: FLIR T640 (SN 55912229) (CALIBRATION DUE DATE: 26 DEC 2026)
ULTRASOUND	: UE 10000 MPH (SN 105249) (CALIBRATION DUE DATE: 26 DEC 2026)

PREPARED BY	
NAME OF CONTRACTOR	: EET ENGINEERING SERVICES SDN BHD
ADDRESS	: NO.38, JALAN SS19/1D,
	: 47500, SUBANG JAYA, SELANGOR.

SUBSTATION SIGNBOARD



EXECUTIVE SUMMARY

NO.	EQUIPMENT	AREA	IR (Abs T/ $\hat{a}^{\dagger}$ T)	US (dB)	DEFECT
1.	RMU SF6 TAMCO	OVERVIEW	-	-	-
		OVERVIEW TOP	-	-	-
		OVERVIEW BOTTOM	-	-	-
	PANEL CCH00347 KTRS TNB	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	
	PANEL CCH00346 LOJI AIR	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	
	PANEL CCH00345 SSU HABU	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	

VISUAL DEFECT SUMMARY

NO.	EQUIPMENT	DEFECT DESCRIPTION	ADDITIONAL REMARKS
1	SUBSTATION	CPR POSTER OLD VERSION	SWG BAY