

CHHATTISGARH STATE INDUSTRIAL DEVELOPMENT CORPORATION

Drishti - Automated Land Monitoring Report


Project: Detection - KHAPRI KHURD
Area: KHAPRI KHURD
Generated: 2026-02-12 05:29 UTC
Total Plots Detected: 40

Compliance Summary

Metric	Count
Total Detected Plots	40
Compliant	0
Encroachments	0
Boundary Mismatches	0
Vacant Plots	1
Unauthorized Development	0

Plot Schematic

Detection - KHAPRI KHURD - KHAPRI KHURD



Plot Inventory

#	Label	Category	Area (sq.m)	Area (sq.ft)	Perimeter (m)	Status
1	Plot 1	Plot	2337.9	25164.8	448.9	Active
2	Plot 4	Plot	13903.9	149660.2	545.3	Active
3	Plot 8	Plot	3726.3	40109.9	246.3	Active
4	Vegetation 4	Vegetation	3550.7	38219.7	233.5	Active
5	Vegetation 6	Vegetation	2350.0	25295.1	284.8	Active
6	Plot 11	Plot	1565.0	16845.3	160.4	Active
7	Vegetation 9	Vegetation	323.3	3479.6	85.9	Active
8	Plot 14	Plot	1327.8	14292.5	195.4	Active
9	Plot 16	Plot	895.8	9642.7	132.1	Active
10	Plot 17	Plot	586.2	6309.6	110.7	Active
11	Vegetation 10	Vegetation	648.9	6984.3	119.7	Active
12	Water 1	Water	424.3	4567.4	83.9	Active
13	Water 2	Water	419.3	4513.4	83.4	Active
14	Plot 27	Plot	87.8	945.2	45.6	Active
15	Plot 30	Plot	245.2	2638.9	64.4	Active
16	Vegetation 16	Vegetation	346.7	3732.0	367.8	Active
17	Plot 33	Plot	183.2	1972.3	54.8	Active
18	Vegetation 21	Vegetation	124.9	1344.7	45.2	Active
19	Vegetation 1	Vegetation	1605.3	17279.9	196.1	Active
20	Vegetation 2	Vegetation	1163.8	12526.5	262.4	Active
21	Plot 3	Plot	7686.7	82739.0	450.3	Active
22	Plot 4	Plot	6724.6	72383.2	374.4	Active
23	Plot 5	Plot	5761.2	62012.8	345.1	Active

24	Plot 6	Plot	5763.8	62041.2	324.1	Active
25	Plot 7	Plot	3359.8	36164.1	235.7	Active
26	Plot 9	Plot	2483.2	26728.4	204.2	Active
27	Plot 10	Plot	919.8	9900.1	122.6	Active
28	Plot 12	Plot	937.9	10095.8	122.5	Active
29	Open Land 1	Open_land	900.2	9689.4	148.3	Active
30	Plot 23	Plot	155.5	1673.4	66.4	Active
31	Plot 32	Plot	226.0	2432.2	81.8	Active
32	Vegetation 37	Vegetation	149.9	1613.1	51.2	Active
33	Vegetation 39	Vegetation	157.2	1692.1	56.4	Active
34	Vegetation 46	Vegetation	119.2	1282.6	48.8	Active
35	Building 1	Building	126.8	1365.0	48.6	Active
36	Vegetation 48	Vegetation	117.4	1264.0	45.8	Active
37	Vegetation 51	Vegetation	20.4	219.5	19.7	Active
38	Plot 36	Plot	99.9	1075.8	40.4	Active
39	Vegetation 53	Vegetation	88.6	953.5	38.1	Active
40	Building 2	Building	109.7	1180.7	45.8	Active

Deviation Details

Plot 723 - VACANT

Plot appears largely vacant: 88201.7 sq.m (97.4%) of allotted area is unused.

Detected Area	2337.89 sq.m
Basemap Area	90539.64 sq.m
Encroachment Area	0.0 sq.m
Vacant Area	88201.75 sq.m
Match %	2.58%

This report was generated by Drishti - Automated Land Monitoring System for CSIDC. Data accuracy depends on satellite imagery resolution and SAM model predictions.