

Inspection Report

Inspection ID: 1


Product Category: bottle
Anomaly Score: 45.7088
Severity: MODERATE
Timestamp: 2026-08-04 14:04:24

Recommendations:

- Reject product.
- Inspect relevant production line station.
- Schedule routine maintenance check.



Original Image



Anomaly Heatmap