

# VEHICLE DAMAGE REPORT — SAMPLE

## Vehicle Information

|                 |                            |
|-----------------|----------------------------|
| Vehicle Number  | OD-15-AB-1234              |
| Vehicle         | Maruti Suzuki Baleno, 2022 |
| Inspection Date | 21 September 2026          |

## Damage Observations

|                 |                                      |
|-----------------|--------------------------------------|
| Affected Area 1 | Front bumper — cracked and displaced |
| Affected Area 2 | Left headlight — cracked             |
| Affected Area 3 | Left front fender — dented           |

## Assessment

The observed damage is consistent with an impact involving the front-left section of the vehicle. Additional internal damage cannot be ruled out without further inspection.