



# Vehicle Inspection

4.32E+15

Vehicle Info	
Overall PASS/FAIL	
PASS	
Blocker	
Engine photo	

Row ID  
351

PO Number  
INSP-9810-1000-0

Year  
2022

Make  
Lease Plan Test 1

Model  
Lease Plan Test 1

Odometer  
Excellent

License Plate Expiration Date  
2023-09-06

License Plate Number  
12



# Vehicle Inspection

4.32E+15

VIN #
VIN 4.32E+15





# Vehicle Inspection

4.32E+15

## Location

<b>DSP Code/Location Name</b> ABBA
<b>Address</b> Allama Iqbal Town, Lahore, Pakistan
<b>City</b> Lahore

<b>State</b> Punjab
<b>Zip Code</b> 30009
<b>DSP Code/Location Phone Number</b> 2087391486

<b>DSP Code/Location Contact Name</b> Jane Smith
<b>Inspection Time</b> 5:00 AM
<b>Last Route Date</b> 2022-03-10



# Vehicle Inspection

4.32E+15

## Check List Items N/A For Rejection

Does Door Open and Close
Fail
<input checked="" type="checkbox"/> Minimum 1 Key/Fob provided
Mechanical Comments (Dead Battery, Knocking Sounds, Will not stay running, Out of Fuel, etc.)
Pass

Passenger Door Open and Close?
Yes
Side Cargo Door Open and Close?
Yes

How Many Key Fobs
4
Body Damage Comments
No damage



# Vehicle Inspection

4.32E+15

## Driver Front Fender

Damages  
No Damage,

### Driver Front Fender Images





Driver Front Fender Images



## Vehicle Inspection

4.32E+15





Vehicle Inspection

4.32E+15

Driver Front Door

Damages  
No Damages

Fail





# Vehicle Inspection

4.32E+15

Drivers Side	
Damages	
No Damages	

Drivers Side Images



Drivers Side Images



## Vehicle Inspection

4.32E+15





# Vehicle Inspection

4.32E+15

Rear
<div>Damages</div> <div>LIGHT SCRATCHES, SEVERE DAMAGE,</div>

Rear Damage Photos





# Vehicle Inspection

4.32E+15

## PLATE NUMBER

Damages  
No Damages

Number  
12

Plate Photo. If no plate take photo of blank plate location





## Vehicle Inspection

4.32E+15





## Vehicle Inspection

4.32E+15



Number

Plt 523

Plate Photo. If no plate take photo of blank plate location



## Vehicle Inspection

4.32E+15





Vehicle Inspection

4.32E+15

PLATE EXPIRATION DATE

Damages  
No Damages

Date  
2023-09-06

Date  
Sep 22 2023





Vehicle Inspection

4.32E+15

Rear Bumper/Rear Step

Damages  
No Damage,

Pass

Pass



Vehicle Inspection

4.32E+15

TAIL LIGHTS

Damages  
No Damage,

Fail

Pass



# Vehicle Inspection

4.32E+15

## Passenger Side

**Damages**  
No Damage, Amazon Logo Missing ,

Passenger Side Images



Passenger Side Images



## Vehicle Inspection

4.32E+15





# Vehicle Inspection

4.32E+15

## SIDESTEPS

Damages  
No Damages

Photos



Fail

Pass

Photos



## Vehicle Inspection

4.32E+15





# Vehicle Inspection

4.32E+15

## Passenger Front Door

Damages  
No Damages

PASS

Passenger Door Open and Close?  
Yes

Photos





# Vehicle Inspection

4.32E+15

## SIDE MIRRORS

Damages  
No Damages

Pass

Photos







# Vehicle Inspection

4.32E+15

## Passenger Front Fender

Damages  
No Damage,

Passenger Front Fender Images





# Vehicle Inspection

4.32E+15

## Front Bumper/Grille

Damages  
No Damages

Front Bumper/Grille Images





# Vehicle Inspection

4.32E+15

Hood/ Roof Above Windshield

Damages

No Damages

Take Photo of of Roof as best as possible





Vehicle Inspection

4.32E+15

ROOF

Damages  
No Damages

Pass



Vehicle Inspection

4.32E+15

HEAD LIGHTS

Damages  
No Damages

Pass



# Vehicle Inspection

4.32E+15

## TURNSIGNALS

Damages
No Damages

Pass
------



Vehicle Inspection

4.32E+15

OVERALL WHEELS AND HUBCAPS

Damages  
No Damages

Pass



Vehicle Inspection

4.32E+15

UPHOLSTERY AND TRIM

Damages  
BURN HOLE,

Pass





# Vehicle Inspection

4.32E+15

## Interior Cab-Dashboard/Glovebox

**Damages**  
SEVERE DAMAGE,

Fail



# Vehicle Inspection

4.32E+15

## WINDSHIELD INSPECTION

Damages  
No Damages

Pass



# Vehicle Inspection

4.32E+15

## Odometer

**Damages**  
No Damages

**Reading**  
Excellent



# Vehicle Inspection

4.32E+15

## Warning Indicator Lights

Damages  
No Damages

Pass



# Vehicle Inspection

4.32E+15

## Cargo Area

Damages

No Damages

Pass

Side Cargo Door Open and Close?

Yes



Vehicle Inspection

4.32E+15

Blocker Y/N
<div>Damages</div> <div>No Damages</div>
<div>Blocker Reason</div> <div>Engine photo</div>
<div>Yes</div>



Vehicle Inspection

4.32E+15

OVERALL Pass/Fail

Damages  
No Damages

Pass



# Vehicle Inspection

4.32E+15

## Summary

**Body Damage Comments**  
No damage

**Mechanical Comments (Dead Battery, Knocking Sounds, Will not stay running, Out of Fuel, etc.)**  
Pass

**Date**  
25/09/23