Damage Photographs

CLM-2024-1873 · 2023 BMW 540i xDrive · taken 2024-01-22



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Both driver-side doors



4. Close-up — front quarter panel

AUTOSURE · RECEIVED
2024-01-22