Damage Photographs

CLM-2024-2019 · 2020 Ford F-150 XLT · taken 2024-02-24



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Hood 90+ dents



4. Close-up — roof panel

AUTOSURE · RECEIVED
2024-02-24