Damage Photographs

CLM-2024-2238 · 2020 Subaru Outback · taken 2024-01-26



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Hood



4. Close-up — grille

AUTOSURE · RECEIVED
2024-01-26