Damage Photographs

CLM-2024-2384 · 2019 Jeep Grand Cherokee · taken 2024-02-17



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Hood



4. Close-up — roof

AUTOSURE · RECEIVED
2024-02-17