# Damage Photographs

CLM-2024-2457 · 2022 Mazda CX-5 · taken 2024-01-29

IMG_0001.JPG



1. Overall — front three-quarter

IMG_0002.JPG



2. Overall — rear three-quarter

IMG_0003.JPG



3. Close-up — Roof crush

IMG_0004.JPG



4. Close-up — all airbags

AUTOSURE · RECEIVED
2024-01-29