Damage Photographs

CLM-2024-2822 · 2022 Kia Sorento · taken 2024-01-31



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Two tires



4. Close-up — rim

AUTOSURE · RECEIVED
2024-01-31