# Damage Photographs

CLM-2024-2895 · 2021 Toyota Camry · taken 2024-01-28

IMG_0001.JPG



1. Overall — front three-quarter

IMG_0002.JPG



2. Overall — rear three-quarter

IMG_0003.JPG



3. Close-up — Roof dents

IMG_0004.JPG



4. Close-up — windshield shattered

AUTOSURE · RECEIVED
2024-01-28