Contractor visit entry

RECORD / DATE	ASSET / JOB
DOC-002 / 2026-09-22	MC01-P17 / MC-J104
STATUS	SOURCE
Work recorded complete	Fictional maintenance collection

Recorded work

The fictional contractor entry records gasket replacement at the lower flange of MC01-P17, the orange-band circulation pump. A dry visual check at completion is recorded. This document provides no method of work or equipment specification.

Evidence timeline

18 September: IMG-039, AUD-001 and DOC-001 record deposits and dampness. 22 September: AUD-002 and this entry record the contractor update. The original image remains a historical observation.

What this record establishes

The entry establishes what was recorded as done on this date. It is not a warranty, diagnosis or independent verification of the repair. No new photograph of this exact asset was taken for the completion entry.

Record linkage

Attach this job to MC01-P17 only. Calder House has an orange-band green pump under CH02-P01; colour similarity does not transfer the maintenance history between buildings.