Filter visit note

RECORD / DATE	ASSET / JOB
DOC-010 / 2026-09-26	CH02-F02 / CH-J207
STATUS	SOURCE
Added to contractor list	Fictional maintenance collection

Filter observation

The turquoise-band cabinet CH02-F02 contains a dust-loaded pleated filter. IMG-089 and AUD-017 document the observation dated 26 September. A contractor visit is requested; no replacement completion is recorded.

Nearby cabinet

The yellow-band cabinet CH02-P04 has a clean filter in reference image IMG-074. It is a different asset, not the later state of the dusty filter. The colour band must be checked against the structured register.

Cross-building distinction

Mercer Court has a separate yellow-band filter cabinet MC01-F02 with its own completed job history. Its replacement entry does not apply to Calder House.

Record limits

These independently generated photographs are illustrative equipment records. They do not establish exact dimensions, compatible parts, filter performance or any current real-world condition.