Calder House orientation

RECORD / DATE	ASSET / JOB
DOC-012 / 2026-10-03	MULTIPLE / CH-H031
STATUS	SOURCE
Handover record	Fictional maintenance collection

Controls

The closed dark blue cabinet CH02-P05 has two green indicators and sits along the basement corridor. Image IMG-075 and recording AUD-019 locate it. Mercer Court has a different pale grey cabinet.

Other equipment

CH02-P03 is a blue expansion vessel beside a short white cylinder. CH02-P06 is a black water booster below a stainless pressure vessel. These are reference records, not fault diagnoses.

Maintenance list

CH02-I01 has a tear in black foam around a dry copper bend, described in AUD-020 and image IMG-090. Keep it separate from Mercer Court silver-jacket work. CH-J203, CH-J207 and CH-J211 remain requests without completion entries in this pack.

Provenance and boundaries

Calder House is fictional. No real address, access code or tenant information is included. Search this building by strict CH02 metadata filtering, not by guessing the building from appearance.