Northbridge Lettings

Check-out inspection report

Record the condition, cleanliness, contents, defects and photographic evidence observed during a check-out inspection at Flat 8, 168 Alder Lane, Kingshaven, ZZ4 3ZZ.

Check-out report. Appointment date: 25 August 2026. Assessor: Northbridge Lettings.

The assessor confirms that the report reflects their assessment of the property. Signature received: 27 September 2025 14:00:39.

The report describes the main features of the property room by room and records observed defects with photographs. The inspection was visual; inaccessible and loft areas were not inspected. Fixtures and fittings may not have been tested. The report does not provide repair advice or costs and may not identify structural defects.

The report guidance states that at the end of a tenancy the property and contents are expected to be in a similar condition and cleanliness to the start-of-tenancy report. Damage beyond fair wear and tear may require repair or replacement, with costs potentially deducted from the tenant’s deposit. Unsatisfactory cleaning may require professional cleaning, with costs potentially deducted from the deposit. Receipts for repair, replacement or professional cleaning should be retained if required.

The report guidance says the property should be left tidy and cleaning thorough. It refers to cleaning carpets and curtains as required by the agreement; leaving vinyl or tile flooring clean and free from cracks or tears; maintaining decor and repairing added picture hooks, nails, screws or screw holes; removing excessive marks and fingerprints; defrosting, switching off and leaving refrigerators and freezers open; cleaning ovens, hobs, extractor units and microwaves; and tidying gardens where applicable.

The report guidance states smoke and carbon monoxide alarms will have been checked and working as of the report date, and that tenants are responsible for keeping them in working order during the tenancy. Faults other than battery replacement should be reported immediately.

Condition rating guidance: Excellent means unused or new; Good means minor wear with no obvious appearance or function faults; Fair means wear or minor damage; Poor means extensive wear such as stains, marks, rips or chips; Unacceptable means not fit for purpose, badly damaged or faulty.

Cleanliness rating guidance for inspection areas: Excellent means cleaned to a high standard; Good means cleaned to a good standard; Fair means cleaned to a fair standard; Poor means light cleaning is required; Unacceptable means professional cleaning is required. For item cleanliness, Fair, Poor and Unacceptable ratings direct the reader to the issues and photographs.

Lounge description: Double sofa; grey carpets; off-white coloured walls; all clean and in good order. Two spotlights not working. Cieling tile water damage. Maintenance.

Bedroom description: 3/4 bed with mattress protector; double wardrobe; TV on wall bracket; remote; table and chair. All in good clean order.

Bathroom description: Walk-in shower and screen; towel rail radiator; toilet; toilet brush; sink on vanity unit; small wall mirror. Room is not clean and some items left. Items left. Cleaning required.

Assessor declaration: The report reflects the assessor’s assessment of the property. Assessor: Northbridge Lettings. Email: assessor@example.com.

Inspection area	Condition	Cleanliness	Defects	Photos
Lounge area	Good	Good	2	7

Inspection area	Condition	Cleanliness	Defects	Photos
Bedroom area	Fair	Fair	0	4
Bathroom	Fair	Poor	2	20

Area	Inspection date	Condition	Cleanliness	Description and recorded issues
Lounge area	25 August 2026	Good	Good	Double sofa; grey carpets; off-white coloured walls; all clean and in good order. Two spotlights not working. Cieling tile water damage. Maintenance.
Bedroom area	25 August 2026	Fair	Fair	3/4 bed with mattress protector; double wardrobe; TV on wall bracket; remote; table and chair. All in good clean order.
Bathroom	25 August 2026	Fair	Poor	Walk-in shower and screen; towel rail radiator; toilet; toilet brush; sink on vanity unit; small wall mirror. Room is not clean and some items left. Items left. Cleaning required.

General detector details	Tested?	General detector comments
	No	

Category	Area	Condition	Cleanliness	Defect
General	Lounge area	Good	Good	Two spotlights not working
Cleaning	Bathroom	Fair	Poor	Items left
Cleaning	Bathroom	Fair	Poor	Cleaning required
Maintenance	Lounge area	Good	Good	Cieling tile water damage

Observations

- The inspection appointment and room inspections are dated 25 August 2026.
- Lounge condition and cleanliness were each rated Good. Two defects were recorded: two spotlights not working and water damage to a ceiling tile.
- Bedroom condition and cleanliness were each rated Fair; no defects were recorded.
- Bathroom condition was rated Fair and cleanliness Poor. Two defects were recorded: items left and cleaning required.
- The detector entry shows Tested? No. No detector details or comments were recorded.
- The report contains 7 lounge photographs, 4 bedroom photographs and 20 bathroom photographs.

Findings

- General defect: Lounge — two spotlights not working; condition Good; cleanliness Good.
- Maintenance defect: Lounge — Cieling tile water damage; condition Good; cleanliness Good.
- Cleaning defects: Bathroom — items left and cleaning required; condition Fair; cleanliness Poor.

Conclusions

- The check-out report identifies two lounge maintenance issues and bathroom cleaning and belongings issues.
- No defects were recorded for the bedroom.

Image evidence

Neutral image placeholder

Lounge photo 1 of 7: Shows the lounge seating area, including a double sofa, carpet and walls.

Neutral image placeholder

Lounge photo 2 of 7: Shows the lounge doorway and part of the room, including the sofa and carpet.

Neutral image placeholder

Lounge photo 3 of 7: Shows a table and chair beside a wall and doorway.

Neutral image placeholder

Lounge photo 4 of 7: Shows the lounge ceiling and spotlight fittings.

Neutral image placeholder

Lounge photo 5 of 7: Shows the lounge carpet, sofa and doorway.

Neutral image placeholder

Lounge photo 6 of 7: Shows ceiling spotlights; the report identifies two spotlights as not working.

Neutral image placeholder

Lounge photo 7 of 7: Shows a ceiling tile area; the report identifies water damage.

Neutral image placeholder

Bedroom photo 1 of 4: Shows the bed and part of the bedroom, including the window.

Neutral image placeholder

Bedroom photo 2 of 4: Shows the bed and window.

Neutral image placeholder

Bedroom photo 3 of 4: Shows the bed, wardrobe, table and chair.

Neutral image placeholder

Bedroom photo 4 of 4: Shows the table and chair area and wall-mounted television.

Neutral image placeholder

Bathroom photo 1 of 20: Shows the shower enclosure and part of the bathroom.

Neutral image placeholder

Bathroom photo 2 of 20: Shows the toilet and towel rail radiator.

Neutral image placeholder

Bathroom photo 3 of 20: Shows the bathroom ceiling and fittings.

Neutral image placeholder

Bathroom photo 4 of 20: Shows the toilet and vanity sink area.

Neutral image placeholder

Bathroom photo 5 of 20: Shows a mat and footwear left on the bathroom floor, consistent with the recorded items-left issue.

Neutral image placeholder

Bathroom photo 6 of 20: Shows the vanity sink area and items on the basin, consistent with the recorded items-left issue.

Neutral image placeholder

Bathroom photo 7 of 20: Close view of the basin tap and sink area, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 8 of 20: Shows a bathroom wall and ceiling junction, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 9 of 20: Close view of a bathroom fitting, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 10 of 20: Shows a tiled bathroom corner and fittings, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 11 of 20: Close view of bathroom pipework and fittings, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 12 of 20: Shows a bathroom wall and fitting, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 13 of 20: Shows a shower fitting, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 14 of 20: Shows the shower head and surrounding area, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 15 of 20: Shows a ceiling fitting and wall junction, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 16 of 20: Shows the shower enclosure and adjoining wall, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 17 of 20: Shows the shower enclosure corner and surrounding surfaces, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 18 of 20: Close view of the shower enclosure frame and adjacent surfaces, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 19 of 20: Shows a bathroom surface beside the shower enclosure, included in the cleaning-required photographs.

Neutral image placeholder

Bathroom photo 20 of 20: Shows the towel rail radiator area and nearby floor, included in the cleaning-required photographs.