PHOTO LOG

Photo 1: close view of damage, quarter panel.

Photo 2: close view of damage, door glass.

Photo 3: close view of damage, front door panel.

Photo 4: close view of damage, rocker panel.