## Thermographic Inspection Report (fictional)

Location: Electrical Room 1
Equipment: Panel P1
Component: Full Panel

Image Date: 03/11/2025
Max Temp: 131.7
Possible Cause: Loose Connection(s)

## Thermographic Inspection Report (fictional)

Location: Electrical Room 1
Equipment: Panel P2
Component: Circuit 11

Image Date: 03/11/2025
Max Temp: 131.7
Possible Cause: Loose Connection(s)

## Thermographic Inspection Report (fictional)

Location: Pump Room
Equipment: Starter S3
Component: Full Starter

Image Date: 03/11/2025
Max Temp: 131.7
Possible Cause: Loose Connection(s)