iSurvix | Survey evidence drawings

SYN-HARDENING-20261021 / Drawing register and verification notes

Survey documentation. Each drawing is evidence-bound and requires authorised technical review.

Recorded item	Finding / verification status	Source evidence
SV-002 | Site layout	1 sheet(s) | Measured records + verification schedule	2 recorded findings; sources linked in geometry.json
SV-003 | Shelter, equipment and cable routes	1 sheet(s) | Evidence schedule only / Not to Scale	1 recorded findings; sources linked in geometry.json
SV-004 | Tower elevation, sections and platforms	1 sheet(s) | Evidence schedule only / Not to Scale	1 recorded findings; sources linked in geometry.json
SV-005 | Antenna levels and sectors	Not generated - supporting information missing	No geometry or connections assumed
SV-006 | Equipment schedule and mounting records	1 sheet(s) | Evidence schedule only / Not to Scale	6 recorded findings; sources linked in geometry.json
SV-007 | Enlarged mounting connections	Not generated - supporting information missing	No geometry or connections assumed
SV-008 | Power single-line records	Not generated - supporting information missing	No geometry or connections assumed
SV-009 | Rectifier and MDB distribution	Not generated - supporting information missing	No geometry or connections assumed
SV-010 | Roxtec and hatchplate arrangements	Not generated - supporting information missing	No geometry or connections assumed
SV-011 | Grounding arrangement	Not generated - supporting information missing	No geometry or connections assumed

Recorded item	Finding / verification status	Source evidence
Design basis	No structural/electrical design performed. No governing design code or load combinations claimed.	A design basis and separate calculations are needed for engineering design.
Survey origin	Survey 1 | 2026-10-21	5 linked evidence references
Drawing symbols	isurvix-generic-symbols-1	Generic measured envelopes; Typical - verify against site.
Verification	6 missing sheet categories; 0 warnings	Review missing information and conflicts before release.

Evidence record only. No structural capacity, electrical safety or code compliance assessment.

Unknown dimensions and concealed connections have not been inferred. Review sources before use.

NORTH: not established unless recorded in the source.

Use the stated scale only. Do not scale evidence schedules.

Revision 001 | 2026-10-21 | Authorised release

Previous output revisions remain preserved in the survey history.

RELEASED - Survey record only

Project: SYNTHETIC integrated survey project

Site: SYN-HARDENING-20261021

Drawing register and verification notes

SV-001 | Rev 001 | 2026-10-21 | Sheet 1/5

Scale: Not to Scale

Prepared: synthetic_integration_engineer	Checked: synthetic_integration_qa	Approved: synthetic_integration_lead

SYN-HARDENING-20261021 / Site layout

Measured record diagram - scale 1:20 at A3

Recorded item	Finding / verification status	Source evidence
Site ID	SYN-HARDENING-20261021 | Confirmed from evidence	evidence photo:1 | original; evidence photo:2 | original
C-01 verified test envelope	Confirmed measured record (m); site_measured	evidence photo:1



C-01 verified test envelope

0 1000 mm

Generic envelopes: Typical - verify against site.

Evidence record only. No structural capacity, electrical safety or code compliance assessment.

Unknown dimensions and concealed connections have not been inferred. Review sources before use.

NORTH: not established unless recorded in the source.

Use the stated scale only. Do not scale evidence schedules.

Revision 001 | 2026-10-21 | Authorised release

Previous output revisions remain preserved in the survey history.

RELEASED - Survey record only

Project: SYNTHETIC integrated survey project

Site: SYN-HARDENING-20261021

Site layout

SV-002 | Rev 001 | 2026-10-21 | Sheet 2/5

Scale: 1:20 at A3

Prepared: synthetic_integration_engineer	Checked: synthetic_integration_qa	Approved: synthetic_integration_lead

iSurvix | Survey evidence drawings

SYN-HARDENING-20261021 / Shelter, equipment and cable routes

Evidence schedule - no unsupported positions, concealed connections or exact profiles.

Recorded item	Finding / verification status	Source evidence
cable_route	none recorded | needs_review	photo photo:2 | original

Evidence record only. No structural capacity, electrical safety or code compliance assessment.

Unknown dimensions and concealed connections have not been inferred. Review sources before use.

NORTH: not established unless recorded in the source.

Use the stated scale only. Do not scale evidence schedules.

Revision 001 | 2026-10-21 | Authorised release

Previous output revisions remain preserved in the survey history.

RELEASED - Survey record only

Project: SYNTHETIC integrated survey project

Site: SYN-HARDENING-20261021

Shelter, equipment and cable routes

SV-003 | Rev 001 | 2026-10-21 | Sheet 3/5

Scale: Not to Scale

Prepared: synthetic_integration_engineer	Checked: synthetic_integration_qa	Approved: synthetic_integration_lead

SYN-HARDENING-20261021 / Tower elevation, sections and platforms

Evidence schedule - no unsupported positions, concealed connections or exact profiles.

Recorded item	Finding / verification status	Source evidence
Recorded tower height	Not recorded | Missing	No source - needs verification

Evidence record only. No structural capacity, electrical safety or code compliance assessment.

Unknown dimensions and concealed connections have not been inferred. Review sources before use.

NORTH: not established unless recorded in the source.

Use the stated scale only. Do not scale evidence schedules.

Revision 001 | 2026-10-21 | Authorised release

Previous output revisions remain preserved in the survey history.

RELEASED - Survey record only

Project: SYNTHETIC integrated survey project

Site: SYN-HARDENING-20261021

Tower elevation, sections and platforms

SV-004 | Rev 001 | 2026-10-21 | Sheet 4/5

Scale: Not to Scale

Prepared: synthetic_integration_engineer	Checked: synthetic_integration_qa	Approved: synthetic_integration_lead

SYN-HARDENING-20261021 / Equipment schedule and mounting records

Evidence schedule - no unsupported positions, concealed connections or exact profiles.

Recorded item	Finding / verification status	Source evidence
measurement	Not recorded | needs_review	photo photo:1 | original
Survey contact	Synthetic Engineer | Reported	No source - needs verification
Cabinet manufacturer	TestCo | Confirmed from evidence	evidence photo:1 | original
Recorded cabinet width	1.2 m | Reported	No source - needs verification
Recorded cabinet height	2 m | Reported	No source - needs verification
Cabinet inspection result	Not recorded | Missing	No source - needs verification

Evidence record only. No structural capacity, electrical safety or code compliance assessment.

Unknown dimensions and concealed connections have not been inferred. Review sources before use.

NORTH: not established unless recorded in the source.

Use the stated scale only. Do not scale evidence schedules.

Revision 001 | 2026-10-21 | Authorised release

Previous output revisions remain preserved in the survey history.

RELEASED - Survey record only

Project: SYNTHETIC integrated survey project

Site: SYN-HARDENING-20261021

Equipment schedule and mounting records

SV-006 | Rev 001 | 2026-10-21 | Sheet 5/5

Scale: Not to Scale

Prepared: synthetic_integration_engineer	Checked: synthetic_integration_qa	Approved: synthetic_integration_lead