WARRANTY CLAIM FORM

Submitted through the customer claim portal

Claim ID: WC-2026-0411

Claimant Name: Hannah Okoro

Claimant ID: USR-4471

Policy Number: POL-TECH-CARE-01

Product: Nimbus X15 128GB

Serial Number: NMB-X15-640218

Purchase Date: 2025-06-12

Incident Date: 2026-09-29

Claimed Repair Amount: INR 18,900.00

Details of the problem

Problem Description: The rear camera shows a black screen in every camera app. The front camera still works.

Customer Statement: The rear camera stopped working on 29 September during normal use. An authorised repair centre inspected the phone two days later. Invoice and report attached.

OFFICIAL RETAIL INVOICE

Store: Metro Digital Store #118
Customer: Hannah Okoro
Invoice Number: INV-77208
Purchase Date: 2025-06-12
Item Description: Nimbus X15 128GB
Serial Number: NMB-X15-640218
Policy Number: POL-TECH-CARE-01
Amount Paid: INR 69,999.00

AUTHORIZED SERVICE CENTER REPORT

Service Provider: FixRight Authorized Care
Technician ID: TECH-552
Date of Inspection: 2026-10-01
Client: Hannah Okoro
Device: Nimbus X15 128GB
Serial Number: NMB-X15-640218
Diagnosis: Rear camera module failure; image sensor returns no signal. Housing undamaged.
Estimated Cost: INR 18,900.00