

Sample Inspection Report

Property Address: 123 Sample Street

Inspector: John Doe

Date: 10 March 2026

Observation 1: Visible crack observed on the living room wall near the window.

Observation 2: Dampness detected on the bedroom ceiling.

Observation 3: Minor paint peeling noticed in the kitchen area.

Inspection Images

