

Worksheet

Ref Number:	BLI3103209-mar
Date:	2026-03-31 16:31:47
Confirmed Order:	Yes
Customer:	Mr Chris Dunn Villa 438Arabella 2 christopherdunn00@gmail.com 0502298691
Salesperson:	Maria Blindtex Blindtex DMCC
Installation Date:	2026-04-10
Installation Time:	02:00 PM
Installation Hours:	3 hours

Room	Details	Width	Height	Measure Type	Chain Length
------	---------	-------	--------	--------------	--------------

1 of 4
Staircase #1

Staircase - 1
Quantity: 1
Roller Basix
Basix Collection
SHA015 (Dove)
Extras:
Control Side : Right
Roll Direction : Back
Fixing : Top
System Size : Large

1200mm

3350mm

Blind Size

0mm

[Special Instructions: Change fabric used existing mechanism and cassette.](#)

2 of 4
Staircase #2

Staircase - 2
Quantity: 1
Roller Basix
Basix Collection
SHA015 (Dove)
Extras:
Control Side : Right
Roll Direction : Back
Fixing : Top
System Size : Large

1200mm

2430mm

Blind Size

0mm

[Special Instructions: Change fabric used existing mechanism and cassette.](#)

3 of 4	Living room repair cost - 1	1000mm	1000mm	Blind Size	0mm
Living room repair cost #1	Quantity: 1 Alteration Repair Roller (existing mechanism)				
	Special Instructions: Repair living room bottom bar 1230x3080.				

4 of 4	Staircase Scaffolding - 1	1000mm	5000mm	Blind Size	0mm
Staircase Scaffolding #1	Quantity: 1 Ladders Scaffold Scaffolding Lader-Scaf Extras: Rental per day : 7M Scaffold				

Remarks: Customer confirmed fabric SHA015 in staircase Dispatch on april 7

Product	Details	Total Metres
---------	---------	--------------