

Visual vehicle inspection report

Findings at the time of inspection. See the overview for priorities and next steps.

VEHICLE		REPORT REFERENCE	
2021 Sample Touring Sedan		PPI-DEMO-2026-001 / v1	
VIN	ODOMETER	INSPECTION DATE	
SAMPLE - NO REAL VIN	48,210 mi	Sep 22, 2026	

✔ Checked ⚠ Monitor ⚠ Service recommended 🚨 Urgent ? Unknown / not inspected

N/A = not applicable. A missing or unavailable check is never marked as checked.

IDENTITY & EXTERIOR	
✔ Identity / title / history	OK
⚠ Paint / panels / body damage	Watch
✔ Windshield	OK
✔ Exterior lamps / lenses	OK
CABIN & CONTROLS	
✔ Seats / upholstery / adjustments	OK
✔ Carpet / floor mats	OK
✔ Interior odors	OK
✔ Windows / door locks	OK
✔ Air conditioning / heat	OK
✔ Infotainment / other electrical	OK
DRIVE & DIAGNOSTICS	
✔ Starting / transmission	OK
✔ Braking during road test	OK
✔ Road vibration / noise	OK
✔ Dashboard / warning lamps	OK
✔ Diagnostic scan findings	OK
ENGINE & FLUIDS	
✔ Engine-bay fluid / coolant leaks	OK
✔ Idle noise / engine concerns	OK
✔ Drive belt	OK
✔ Battery terminals	OK
? Fluids observed	Unknown*
BRAKES, CHASSIS & OTHER	
✔ Pad estimate / visible rotors	OK
✔ Steering / tracking	OK
✔ Suspension / ride	OK
? Frame / underside / exhaust	Unknown*
✔ Modifications / other concerns	OK

* Partial: see uninspected items in the overview.

INSPECTOR CERTIFICATION

✔ I certify that the observations and answers in this inspection are accurate to the best of my knowledge and ability.

Jordan Lee | Technician (fictional)

Sep 22, 2026 10:24 ET | Sample only

TIRES & WHEELS	
Placard: 225/50R17 F/R 34 psi cold	
FRONT LEFT 🚨 Urgent Tread: 5/32 in 4.0 mm Pressure: 34 psi (cold) Size: 225/50R17 Load / speed: 98 / V DOT: 0224 Cracking: None ✔ Wear: Even ✔ Tire / rim: Object / rash Fitment: Matches placard	FRONT RIGHT ✔ Checked Tread: 6/32 in 4.8 mm Pressure: 34 psi (cold) Size: 225/50R17 Load / speed: 98 / V DOT: 0224 Cracking: None ✔ Wear: Even ✔ Tire / rim: None / none Fitment: Matches placard
REAR LEFT ⚠ Service Tread: 3/32 in 2.4 mm Pressure: 34 psi (cold) Size: 215/50R17 Load / speed: 98 / V DOT: 0519 Cracking: Significant ⚠ Wear: Mild uneven ⚠ Tire / rim: None / none Fitment: Differs from placard	REAR RIGHT ✔ Checked Tread: 6/32 in 4.8 mm Pressure: 34 psi (cold) Size: 225/50R17 Load / speed: 98 / V DOT: 0224 Cracking: None ✔ Wear: Even ✔ Tire / rim: None / none Fitment: Matches placard

BODY DAMAGE MAP	
	⚠ 1 Left front fender Shallow dent; finish intact. ⚠ 2 Right front door Surface scratch; no bare metal.

Inspection overview

Condition, context and practical next steps, organized by inspection category.

VEHICLE 2021 Sample Touring Sedan		REPORT REFERENCE PPI-DEMO-2026-001 / v1	
VIN SAMPLE - NO REAL VIN	ODOMETER 48,210 mi	INSPECTION DATE Sep 22, 2026	

OBSERVATIONS / SIGNIFICANCE / NEXT STEPS

PRIORITY ACTIONS

Replace the front-left tire: a foreign object is confirmed. Schedule replacement of the rear-left tire for significant cracking; verify its fitment.

TIRES & WHEELS Front-left foreign object [T1]. Rear-left cracking and size mismatch [T2]. Left-front rim has cosmetic rash. Replace front-left tire. Rear-left replacement recommended; verify fitment.	BODY & EXTERIOR Shallow dent at the left front fender [B1]; surface scratch at the right front door [B2]. Monitor or arrange cosmetic repair. See damage map 1 and 2.
INTERIOR & CONTROLS Seats, windows, locks, climate controls and interior lights operated during the recorded checks. No action indicated by the completed checks.	ENGINE & FLUIDS No visible engine-bay leak recorded. Transmission fluid could not be checked on this visit. Have transmission fluid checked using the applicable service procedure.
BRAKES & CHASSIS Pad life estimated at 50-75%; rotor surfaces appeared normal. Underbody access was incomplete. Brake thickness was not measured. Arrange an underside review.	ROAD TEST & DIAGNOSTICS No pulling or abnormal vibration recorded. No stored codes reported; supported monitors completed. No additional action indicated by this test record.

SCOPE & EVIDENCE

Complete scope; transmission-fluid and full underbody checks were unavailable. No measured brake lining or battery capacity test. Tire pressure recorded cold. Findings describe observed conditions, not future performance.

Full findings and uploaded photos are available through the optional evidence appendix.