



WILSON ESTATE CARE

Appliance Health Report

Scotsman DCE33 Icemaker

YOUR APPLIANCE SCORE

84%

B • Good - monitor

HOUSEHOLD

Reynolds Estate

SERVICE ADDRESS

1840 Ridgeview Trail, Austin, TX, 78738

DATE OF SERVICE

Feb 27, 2026

TECHNICIAN

Trevor

Appliance Vitals

What are appliance vitals?

Vitals are the useful readings and functional observations recorded during this maintenance visit. They help show whether the appliance was operating within the target used by the technician and identify areas that should be monitored or corrected.

YOUR APPLIANCE SCORE

84% B

Good - monitor

Freeze cycle time

In range

24 min

TARGET / NORMAL

Model guidance

Harvest cycle

In range

Normal

TARGET / NORMAL

Complete harvest

Bin control

In range

Pass

TARGET / NORMAL

Pass

Visit overview

2 checkpoints should be monitored.

Score Breakdown

How this score was calculated

Each applicable checkpoint receives equal weight in this starter report. A rating of 5 earns full points. Lower ratings create the deductions below, so the score can be traced back to the recorded inspection.

Drain System

Pump sound should be monitored.

-5

Filtration

Filter is approaching replacement.

-5

Other checkpoints

Minor normal-condition deductions.

-6

Your appliance score

The icemaker is producing and harvesting normally. Moderate scale was removed during service. The drain pump is operating, but its sound should be compared again at the next visit.

84% B

Inspection Details

Equipment information

Appliance type	Icemaker (IMUC)
Brand	Scotsman
Model	DCE33
Serial	Not recorded
Location	Wet Bar
Next maintenance	Aug 27, 2026

Visit information

Household	Reynolds Estate
Technician	Trevor
Service date	Feb 27, 2026
Service reference	Not linked
Report score	84% B
Report status	Final

Subsystem review

Condition & Sanitation	Pass
Bin and interior condition Clean after service.	Pass 4/5

Water System	Pass
Water supply connections No visible leaks.	Pass 5/5

Drain System	Watch
Drain or pump condition Slight operating noise; monitor.	Watch 3/5

Freeze Performance	Pass
Freeze cycle performance Normal freeze time.	Pass 4/5

Harvest Performance	Pass
Harvest cycle performance Normal harvest.	Pass 4/5

Water Quality	Pass
Scale and water-quality condition Descaled during visit.	Pass 4/5

Airflow & Heat Transfer	Pass
Condenser coil and airflow Coil vacuumed.	Pass 4/5

Filtration	Watch
Filter status Replacement due next visit.	Watch 3/5

Corrective Measures

Corrective measures

! Replace water filter at next visit

! Monitor drain-pump sound

Recommendations

Replace the water filter at the upcoming visit and re-check drain-pump noise.

Maintenance performed

✓ Vacuum condenser coil

✓ Inspect visible water connections

✓ Photograph key components

✓ Descale per manufacturer guidance

✓ Inspect drain or pump

Filters and consumables

PART / SIZE

SCCP5

ACTION

Replacement recommended

PHOTOS RECORDED

3

Report Information

Appliance Health Score

The Wilson Appliance Health Score summarizes the applicable inspection checkpoints entered by the technician. It is intended to make the condition of the appliance easier to understand and to show where deductions occurred. It is not a prediction of remaining appliance life.

Operating vitals

Recorded temperatures, cycle observations, sealing checks, airflow conditions, water flow, drain performance, and other readings vary by appliance type. Targets shown in this report are entered by the technician for the specific equipment and test performed.

Subsystem review

Subsystem categories group related components and functions, such as temperature performance, water systems, filtration, controls, airflow, drainage, connections, and safety. "Pass" means no action was identified from the recorded inspection. "Watch" identifies an item to monitor. "Action" identifies an item that should be corrected or evaluated through a separate repair order.

Scope and limitations

This report records visible conditions, accessible components, readings, and functional observations made during the maintenance visit. It is not a guarantee against future failure, and it does not replace manufacturer instructions, a repair diagnosis, code inspection, or destructive disassembly.

Service Summary

SERVICE SUMMARY

Routine cleaning and maintenance completed. No immediate repair was required.

Technician condition summary

The icemaker is producing and harvesting normally. Moderate scale was removed during service. The drain pump is operating, but its sound should be compared again at the next visit.

Next planned interval

Aug 27, 2026

The office will use the maintenance dashboard to prompt scheduling and payment review at the appropriate interval.

Photo record

3 photos associated with this report in the production workflow.

TECHNICIAN

Trevor

DATE

Feb 27, 2026

REPORT REFERENCE

report_reynolds_1