DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

Date:	11/07/2026	**Customer:**	Vivek kumar	**Phone:**	9816377281
Vehicle:	NEW THAR LXT D MT 2WD HT BS_6.2	**Color:**	Stealth Black	**Year:**	2026
Engine No:	0	**Chassis:**	0	**Odometer:**	71

INSPECTION CHECKLIST

BODY EXTERIOR GLASS

ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES

ITEM	Y	X	!
Front right tyre	Y		
Front left tyre	Y		
Rear left tyre	Y		
Rear right tyre	Y		
Spare tyre	Y		

INTERIOR & LUGGAGE COMPARTMENT

ITEM	Y	X	!
Seat mechanism	Y		
Seat belts	Y		
Internal mirrors	Y		
Boot/tailgate lock	Y		

ELECTRICAL CONTROLS

ITEM	Y	X	!
Ignition lock/starting system	Y		
Battery charging system Headlights	Y		
Side lights/running lights	Y		
Rear lights & number plate illumination	Y		
Brake lights	Y		
Indicator & hazard lights	Y		
Reverse & fog lights	Y		
Auxiliary lights	Y		
Panel lights/dashboard illumination	Y		
Switches & controls	Y		
Instrument/controls function Horn	Y		
Windows & sunroof operation	Y		
Wipers & jet washers Brakes	Y		
Master cylinder security	Y		
Servo/power system	Y		
Flexible hoses	Y		
Pipes/unions & connections	Y		
Discs & pads	Y		
Hand brake operation/adjustments	Y		
Hand brake linkage Pedal/linkage	Y		

ENGINE COMPARTMENT

ITEM	Y	X	!
Coolant level	Y		
Hoses & pipes	Y		
Drive belts	Y		
Water pump	Y		
Power steering fluid level	Y		
Clutch fluid level	Y		
Brake fluid level	Y		
Engine oil level	Y		
Engine mounts	Y		
Turbo/supercharger	Y		
Fuel pump & pipes	Y		
Accelerator linkage	Y		
Cold starting	Y		
Fast idle when engine cold	Y		
Noise level when engine cold	Y		
Excess fumes/smoke	Y		

CLUTCH & TRANSMISSION

ITEM	Y	X	!
Cables/adjustment	Y		
Hydraulic system	Y		
Linkages (check for signs of wear)	Y		
Casings Mountings	Y		
Drive shaft assemblies	Y		
Universal & sliding joints	Y		
Clutch backlash	Y		
Rubber gaiters Prop-shaft(s)	Y		
Bearings & supports	Y		

EXHAUST SYSTEM

ITEM	Y	X	!
Inlet manifold	Y		
Outlet manifold Pipes Silencer(s)	Y		
Heat shields & mountings	Y		
Joints & couplings	Y		
Catalytic converter	Y		
Overall system condition	Y		

FUEL SYSTEM

ITEM	Y	X	!
Fuel tank	Y		
Fuel tank fixings	Y		
Fuel lines	Y		
Breather pipes	Y		

SUSPENSION, UNDERFRAME & STEERING

ITEM	Y	X	!
Steering joints & ball joints	Y		
Chassis members	Y		
Power steering	Y		
Wheels, hubs & bearings	Y		
Springs & suspension unit	Y		
Pipes & hoses	Y		
Dampers & bushes Gaiters	Y		
Sub frames & mountings	Y		
Suspension arms, mountings & fixings	Y		
Tie bars & anti-roll bars	Y		
Anti roll-bar	Y		
Evidence of floor/chassis corrosion	Y		
Bumper stops & gaiters	Y		

ROAD TEST

ITEM	Y	X	!
Engine - performance	Y		
Engine - noise	Y		
Engine - excessive fumes or smoke	Y		
Evidence of overheating	Y		
Gearbox operation & noise level	Y		
Final drive operation & noise level	Y		
Clutch operation	Y		
Cooling fan operation	Y		
Instruments & controls functioning	Y		

GENERAL STEERING & HANDLING

ITEM	Y	X	!
Footbrake operation	Y		
Hand brake operation	Y		
Suspension noise	Y		
Road holding stability	Y		

CONVENIENCE

ITEM	Y	X	!
Warning lights	Y		
Owners manual	Y		
Service book & history	Y		
Keys & remote controls	Y		


LEAKAGE INSPECTION

Brake Fluid Leakage	NOT FOUND
Coolant Leakage	NOT FOUND
Engine Oil Leakage	NOT FOUND
Engine Underside Leak	NOT FOUND
External Engine Leak	NOT FOUND
Fuel Leakage	NOT FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND


DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

TOP VIEW




SIDE VIEW



INTERIOR VIEW



BOOT VIEW



No damages marked.

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

Vivek kumar

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

VEHICLE IMAGES — NEW THAR LXT D MT 2WD HT BS_6.2

Front View



1783771569897-d8f61b027e6f4d36.jpeg

Rear View



1783771605903-19f49cb970351743.jpeg

Left Side View



1783771638600-382a0612c98bb449.jpeg

Right Side View



1783771660351-81ff6ebab2faf813.jpeg

Interior



1783771686941-285654c98e0da6eb.jpeg

Dashboard




1783771714893-9188eb805479a182.jpeg

Engine



1783771733953-1f0d0de43a968529.jpeg

Boot Space



1783771808597-7c9623ee22aaeac5.jpeg

Stepney / Spare Wheel



1783771857495-c9b24f1ca3fed1f4.jpeg

Tyre - Front Left




1783771969607-9b56683f8bb7befe.jpeg

Tyre - Front Right



1783772004936-f131056f2384ca8d.jpeg

Tyre - Rear Left



1783772056149-b1291a62863bf9e2.jpeg

Tyre - Rear Right



1783772082287-7d74258c1b95bc7f.jpeg

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US :

INFO LINE : +91-86798-00074 / +91-98160-36880

MAIL : INFO@DETAILINGGARAGE.IN