DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

Date:	07/08/2026	**Customer:**	Mr Madan lal thakur	**Phone:**	6239479531
Vehicle:	Mahindra Scorpio-N D AT 2WD Z8T 7S WQ	**Color:**	White	**Year:**	2026
Engine No:	YGT4F75344	**Chassis:**	MA1TJ2YGTT6F61118	**Odometer:**	18

INSPECTION CHECKLIST

BODY EXTERIOR GLASS

ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES

ITEM	Y	X	!
Front right tyre	Y		
Front left tyre	Y		
Rear left tyre	Y		
Rear right tyre	Y		
Spare tyre	Y		

INTERIOR & LUGGAGE COMPARTMENT

ITEM	Y	X	!
Seat mechanism	Y		
Seat belts	Y		
Internal mirrors	Y		
Boot/tailgate lock	Y		

ELECTRICAL CONTROLS

ITEM	Y	X	!
Ignition lock/starting system	Y		
Battery charging system Headlights	Y		
Side lights/running lights	Y		
Rear lights & number plate illumination	Y		
Brake lights	Y		
Indicator & hazard lights	Y		
Reverse & fog lights	Y		
Auxiliary lights	Y		
Panel lights/dashboard illumination	Y		
Switches & controls	Y		
Instrument/controls function Horn	Y		
Windows & sunroof operation	Y		
Wipers & jet washers Brakes	Y		
Master cylinder security	Y		
Servo/power system	Y		
Flexible hoses	Y		
Pipes/unions & connections	Y		
Discs & pads	Y		
Hand brake operation/adjustments	Y		
Hand brake linkage Pedal/linkage	Y		

ENGINE COMPARTMENT

ITEM	Y	X	!
Coolant level	Y		
Hoses & pipes	Y		
Drive belts	Y		
Water pump	Y		
Power steering fluid level	Y		
Clutch fluid level	Y		
Brake fluid level	Y		
Engine oil level	Y		
Engine mounts	Y		
Turbo/supercharger	Y		
Fuel pump & pipes	Y		
Accelerator linkage	Y		
Cold starting	Y		
Fast idle when engine cold	Y		
Noise level when engine cold	Y		
Excess fumes/smoke	Y		

CLUTCH & TRANSMISSION

ITEM	Y	X	!
Cables/adjustment	Y		
Hydraulic system	Y		
Linkages (check for signs of wear)	Y		
Casings Mountings	Y		
Drive shaft assemblies	Y		
Universal & sliding joints	Y		
Clutch backlash	Y		
Rubber gaiters Prop-shaft(s)	Y		
Bearings & supports	Y		

EXHAUST SYSTEM

ITEM	Y	X	!
Inlet manifold	Y		
Outlet manifold Pipes Silencer(s)	Y		
Heat shields & mountings	Y		
Joints & couplings	Y		
Catalytic converter	Y		
Overall system condition	Y		

FUEL SYSTEM

ITEM	Y	X	!
Fuel tank	Y		
Fuel tank fixings	Y		
Fuel lines	Y		
Breather pipes	Y		

SUSPENSION, UNDERFRAME & STEERING

ITEM	Y	X	!
Steering joints & ball joints	Y		
Chassis members	Y		
Power steering	Y		
Wheels, hubs & bearings	Y		
Springs & suspension unit	Y		
Pipes & hoses	Y		
Dampers & bushes Gaiters	Y		
Sub frames & mountings	Y		
Suspension arms, mountings & fixings	Y		
Tie bars & anti-roll bars	Y		
Anti roll-bar	Y		
Evidence of floor/chassis corrosion	Y		
Bumper stops & gaiters	Y		

ROAD TEST

ITEM	Y	X	!
Engine - performance	Y		
Engine - noise	Y		
Engine - excessive fumes or smoke	Y		
Evidence of overheating	Y		
Gearbox operation & noise level	Y		
Final drive operation & noise level	Y		
Clutch operation	Y		
Cooling fan operation	Y		
Instruments & controls functioning	Y		

GENERAL STEERING & HANDLING

ITEM	Y	X	!
Footbrake operation	Y		
Hand brake operation	Y		
Suspension noise	Y		
Road holding stability	Y		

CONVENIENCE

ITEM	Y	X	!
Warning lights	Y		
Owners manual	Y		
Service book & history	Y		
Keys & remote controls	Y		


LEAKAGE INSPECTION

Brake Fluid Leakage	NOT FOUND
Coolant Leakage	NOT FOUND
Engine Oil Leakage	NOT FOUND
Engine Underside Leak	NOT FOUND
External Engine Leak	NOT FOUND
Fuel Leakage	NOT FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND


DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

TOP VIEW




SIDE VIEW



INTERIOR VIEW



BOOT VIEW



No damages marked.

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

Mr Madan lal thakur

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

VEHICLE IMAGES — Mahindra Scorpio-N D AT 2WD Z8T 7S WQ

Front View



1786099941742-a9327a51b446ea9a.jpeg

Rear View



1786100277283-d6b8d764ddc95a4d.jpeg

Left Side View



1786100312430-a236c2f7e6541558.jpeg

Right Side View



1786100472519-c110156849eedd33.jpeg

Interior



1786100504072-aacd289e3f867f83.jpeg

Dashboard



1786100512585-f1d4609a033b014f.jpeg

Engine



1786100539105-e54f734d90964aa6.jpeg

Boot Space



1786100561629-77c4629216b6e30b.jpeg

Stepney / Spare Wheel



1786100596963-76777cc0de21c927.jpeg

Tyre - Front Left




1786100658966-d8a4e364333cb15c.jpeg

Tyre - Front Right




1786100684177-61b58e3b30ba7fb8.jpeg

Tyre - Rear Left



1786100729124-19f9e86dbcc79d41.jpeg

Tyre - Rear Right



1786100750885-d28d4a07d1c0aa50.jpeg

Underbody



1786100779654-3cd0b87a1a421859.jpeg

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US :

INFO LINE : +91-86798-00074 / +91-98160-36880

MAIL : INFO@DETAILINGGARAGE.IN