

Date:	24/05/2026	Customer:	JAGAT RAVI	Phone:	9817490851
Vehicle:	MARUTI FRONX	Color:	BLACK	Year:	2026
Engine No:	00	Chassis:	MBHKWD13STD860249	Odometer:	9

INSPECTION CHECKLIST

BODY EXTERIOR GLASS			
ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES			
ITEM	Y	X	!
Front right tyre	Y		
Front left tyre	Y		
Rear left tyre	Y		
Rear right tyre	Y		
Spare tyre	Y		

INTERIOR & LUGGAGE COMPARTMENT			
ITEM	Y	X	!
Seat mechanism	Y		
Seat belts	Y		
Internal mirrors	Y		
Boot/tailgate lock	Y		

ELECTRICAL CONTROLS			
ITEM	Y	X	!
Ignition lock/starting system	Y		
Battery charging system	Y		
Headlights	Y		
Side lights/running lights	Y		
Rear lights & number plate illumination	Y		
Brake lights	Y		
Indicator & hazard lights	Y		
Reverse & fog lights	Y		
Auxiliary lights	Y		
Panel lights/dashboard illumination	Y		
Switches & controls	Y		
Instrument/controls function	Y		
Horn	Y		
Windows & sunroof operation	Y		
Wipers & jet washers	Y		
Brakes	Y		
Master cylinder security	Y		
Servo/power system	Y		
Flexible hoses	Y		
Pipes/unions & connections	Y		
Discs & pads	Y		
Hand brake operation/adjustments	Y		
Hand brake linkage Pedal/linkage	Y		

ENGINE COMPARTMENT			
ITEM	Y	X	!
Coolant level	Y		
Hoses & pipes	Y		
Drive belts	Y		
Water pump	Y		
Power steering fluid level	Y		
Clutch fluid level	Y		
Brake fluid level	Y		
Engine oil level	Y		
Engine mounts	Y		
Turbo/supercharger	Y		
Fuel pump & pipes	Y		
Accelerator linkage	Y		
Cold starting	Y		
Fast idle when engine cold	Y		
Noise level when engine cold	Y		
Excess fumes/smoke	Y		

CLUTCH & TRANSMISSION			
ITEM	Y	X	!
Cables/adjustment	Y		
Hydraulic system	Y		
Linkages (check for signs of wear)	Y		
Casings Mountings	Y		
Drive shaft assemblies	Y		
Universal & sliding joints	Y		
Clutch backlash	Y		
Rubber gaiters Prop-shaft(s)	Y		
Bearings & supports	Y		

EXHAUST SYSTEM			
ITEM	Y	X	!
Inlet manifold	Y		
Outlet manifold Pipes Silencer(s)	Y		
Heat shields & mountings	Y		
Joints & couplings	Y		
Catalytic converter	Y		
Overall system condition	Y		

FUEL SYSTEM			
ITEM	Y	X	!
Fuel tank	Y		
Fuel tank fixings	Y		
Fuel lines	Y		
Breather pipes	Y		

SUSPENSION, UNDERFRAME & STEERING			
ITEM	Y	X	!
Steering joints & ball joints	Y		
Chassis members	Y		
Power steering	Y		
Wheels, hubs & bearings	Y		
Springs & suspension unit	Y		
Pipes & hoses	Y		
Dampers & bushes Gaiters	Y		
Sub frames & mountings	Y		
Suspension arms, mountings & fixings	Y		
Tie bars & anti-roll bars	Y		
Anti roll-bar	Y		
Evidence of floor/chassis corrosion	Y		
Bumper stops & gaiters	Y		


ROAD TEST			
ITEM	Y	X	!
Engine - performance	Y		
Engine - noise	Y		
Engine - excessive fumes or smoke	Y		
Evidence of overheating	Y		
Gearbox operation & noise level	Y		
Final drive operation & noise level	Y		
Clutch operation	Y		
Cooling fan operation	Y		
Instruments & controls functioning	Y		

GENERAL STEERING & HANDLING			
ITEM	Y	X	!
Footbrake operation	Y		
Hand brake operation	Y		
Suspension noise	Y		
Road holding stability	Y		


CONVENIENCE			
ITEM	Y	X	!
Warning lights	Y		
Owners manual	Y		
Service book & history	Y		
Keys & remote controls	Y		

LEAKAGE INSPECTION	
Brake Fluid Leakage	NOT FOUND
Coolant Leakage	NOT FOUND
Engine Oil Leakage	NOT FOUND
Engine Underside Leak	NOT FOUND
External Engine Leak	NOT FOUND
Fuel Leakage	NOT FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND

TOP VIEW



SIDE VIEW




INTERIOR VIEW

VEHICLE INSPECTION CHECKLIST



BOOT VIEW



No damages marked.

RECOMMENDATIONS & NOTES

Another Happy Customer Delivery Successfully Inspected by Detailing Garage —

Congratulations to Mr. Jagat Ravi from Hamirpur on the delivery of his brand-new Maruti Fronx from Nexa Hamirpur! <%

100+ Detailed Checkpoints Completed
Full Diagnostic Scan with Professional Scanner
Paint Inspection with Paint Gauge
Tyre Inspection with Tyre Gauge
Full Underbody Inspection
No Fault Codes Found =

Our mission is to ensure every customer receives a perfectly inspected and verified vehicle before delivery.

Done By: Ritchie

Location: Hamirpur, Himachal Pradesh

Contact:

+91-8679400014

+91-8679800074

info@detailinggarage.in(mailto:info@detailinggarage.in)

www.detailinggarage.in(http://www.detailinggarage.in)

Don't take delivery of your new car without a professional PDI inspection!

#DetailingGarage #MarutiFronx #NexaHamirpur #CarDelivery #PDIInspection #CarInspection #ProfessionalPDI #NewCarDelivery #Hamirpur #Himachal-Pradesh #RitchiePDI #VehicleInspection #PaintCheck #DiagnosticScan #CustomerSatisfaction #CarCare #AutomotiveLife #NewCar #Fronx #Nexa

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

RITCHIE

JAGAT RAVI

JAGAT RAVI

DETAILING GARAGETM
DETAILING THAT DEFINES LUXURY

EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US:     

INFO LINE : +91-86798-00074 / +91-98160-36880

MAIL : [INFO@DETAILINGGARAGE.IN](mailto:info@detailinggarage.in)

VEHICLE IMAGES — MARUTI FRONX

Front View



1779608418059-744312876d453705.jpeg

Rear View



1779608425697-807f9df4ba0deaa5.jpeg

Left Side View



1779608432263-d9d638891889112f.jpeg

Right Side View



1779608445228-e75d8188f4087c58.jpeg

Interior



1779608451542-0495e1b7e0337b0c.jpeg

Dashboard



1779608459007-4c200f05f75651de.jpeg

Engine



1779608477054-fb2c0f17d8b41a30.jpeg

Boot Space



1779608487907-57b2bed344cc8a16.jpeg

Stepney / Spare Wheel



1779608492869-db2f7d75ca7f99c0.jpeg

Tyre - Front Left



1779608499562-66e607c91c858ef3.jpeg

Tyre - Front Right



1779608539340-2641d53249b4a022.jpeg

Tyre - Rear Left




1779608544394-b49b446e658de9a3.jpeg

Tyre - Rear Right



1779608557703-4a73ca7d4747afc.jpeg

Underbody



1779608563933-f5c10c7d586d6c7b.jpeg

Other Images

From Hamirpur

VEHICLE
MARUTI FRONX

DEALERSHIP
NEXA HAMIRPUR

VEHICLE INSPECTED WITH 100+ CHECK POINTS

NO FAULT CODE FOUND	FULL DIAGNOSTIC WITH PROFESSIONAL SCANNER	PAINT CHECKED BY PAINT GAUGE
TYRE CHECKED	FULL UNDERBODY	PDI PROFESSIONAL

PDI DONE BY
RITCHIE
PDI PROFESSIONAL

1779608575775-b15c72a4e1d03cda.jpeg

EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US:

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

INFO LINE : +91-86798-00074 / +91-98160-36880

MAIL : INFO@DETAILINGGARAGE.IN