DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

Date:	12/10/2026	**Customer:**	abhiii	**Phone:**	07414929549
Vehicle:	Mahindra 7XO	**Color:**	white	**Year:**	2026
Engine No:	ZFT4E71138	**Chassis:**	T6f38456	**Odometer:**	130

INSPECTION CHECKLIST

BODY EXTERIOR GLASS

ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES

ITEM	Y	X	!
Front right tyre	Y		
Front left tyre	Y		
Rear left tyre	Y		
Rear right tyre	Y		
Spare tyre	Y		

INTERIOR & LUGGAGE COMPARTMENT

ITEM	Y	X	!
Seat mechanism	Y		
Seat belts	Y		
Internal mirrors	Y		
Boot/tailgate lock	Y		

ELECTRICAL CONTROLS

ITEM	Y	X	!
Ignition lock/starting system	Y		
Battery charging system Headlights	Y		
Side lights/running lights	Y		
Rear lights & number plate illumination	Y		
Brake lights	Y		
Indicator & hazard lights	Y		
Reverse & fog lights	Y		
Auxiliary lights	Y		
Panel lights/dashboard illumination	Y		
Switches & controls	Y		
Instrument/controls function Horn	Y		
Windows & sunroof operation	Y		
Wipers & jet washers Brakes	Y		
Master cylinder security	Y		
Servo/power system	Y		
Flexible hoses	Y		
Pipes/unions & connections	Y		
Discs & pads	Y		
Hand brake operation/adjustments	Y		
Hand brake linkage Pedal/linkage	Y		

ENGINE COMPARTMENT

ITEM	Y	X	!
Coolant level	Y		
Hoses & pipes	Y		
Drive belts	Y		
Water pump	Y		
Power steering fluid level	Y		
Clutch fluid level	Y		
Brake fluid level	Y		
Engine oil level	Y		
Engine mounts	Y		
Turbo/supercharger	Y		
Fuel pump & pipes	Y		
Accelerator linkage	Y		
Cold starting	Y		
Fast idle when engine cold	Y		
Noise level when engine cold	Y		
Excess fumes/smoke	Y		

CLUTCH & TRANSMISSION

ITEM	Y	X	!
Cables/adjustment	Y		
Hydraulic system	Y		
Linkages (check for signs of wear)	Y		
Casings Mountings	Y		
Drive shaft assemblies	Y		
Universal & sliding joints	Y		
Clutch backlash	Y		
Rubber gaiters Prop-shaft(s)	Y		
Bearings & supports	Y		

EXHAUST SYSTEM

ITEM	Y	X	!
Inlet manifold	Y		
Outlet manifold Pipes Silencer(s)	Y		
Heat shields & mountings	Y		
Joints & couplings	Y		
Catalytic converter	Y		
Overall system condition	Y		

FUEL SYSTEM

ITEM	Y	X	!
Fuel tank	Y		
Fuel tank fixings	Y		
Fuel lines	Y		
Breather pipes	Y		

SUSPENSION, UNDERFRAME & STEERING

ITEM	Y	X	!
Steering joints & ball joints	Y		
Chassis members	Y		
Power steering	Y		
Wheels, hubs & bearings	Y		
Springs & suspension unit	Y		
Pipes & hoses	Y		
Dampers & bushes Gaiters	Y		
Sub frames & mountings	Y		
Suspension arms, mountings & fixings	Y		
Tie bars & anti-roll bars	Y		
Anti roll-bar	Y		
Evidence of floor/chassis corrosion	Y		
Bumper stops & gaiters	Y		

ROAD TEST

ITEM	Y	X	!
Engine - performance	Y		
Engine - noise	Y		
Engine - excessive fumes or smoke	Y		
Evidence of overheating	Y		
Gearbox operation & noise level	Y		
Final drive operation & noise level	Y		
Clutch operation	Y		
Cooling fan operation	Y		
Instruments & controls functioning	Y		

GENERAL STEERING & HANDLING

ITEM	Y	X	!
Footbrake operation	Y		
Hand brake operation	Y		
Suspension noise	Y		
Road holding stability	Y		

CONVENIENCE

ITEM	Y	X	!
Warning lights	Y		
Owners manual	Y		
Service book & history	Y		
Keys & remote controls	Y		


LEAKAGE INSPECTION

Brake Fluid Leakage	FOUND
Coolant Leakage	FOUND
Engine Oil Leakage	FOUND
Engine Underside Leak	FOUND
External Engine Leak	NOT FOUND
Fuel Leakage	NOT FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND


DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST

TOP VIEW




SIDE VIEW



INTERIOR VIEW



BOOT VIEW



No damages marked.

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:


abhiii

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

PRE-DELIVERY INSPECTION CHECK LIST


VEHICLE IMAGES — Mahindra 7XO

Front View



1791788452214-3c3508577fa048f2.jpg

Rear View



1791788456302-02028064f43312b0.jpg