



Date:	09/03/2026	Customer:	abhiii	Phone:	07414929549
Vehicle:	make Innova	Color:	Grey	Year:	2026
Engine No:	SDFSDFSDFSDF	Chassis:	MBJTYK1STA360731	Odometer:	5km

INSPECTION CHECKLIST

TOP VIEW



SIDE VIEW




INTERIOR VIEW

VEHICLE INSPECTION CHECKLIST



BOOT VIEW



IDENTIFIED DAMAGES

1. S (scratch) on top view - No description
2. S (scratch) on top view - No description
3. S (scratch) on top view - No description

RECOMMENDATIONS & NOTES

Comments / Recommendations
 Comments / Recommendations
 Comments / Recommendations
 Comments / Recommendations
 Comments / Recommendations

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

VEHICLE IMAGES — make Innova

Front View



1773054111993-5c81b30ebc1dbf69.jpg

Rear View



1773054122836-258f97cbdea839e6.jpg

Left Side View



1773054126888-52911c366096c421.jpg

Right Side View



1773054132801-5d7fc7ba7cc12694.jpg

Interior



1773054137455-75c38e16e16d3540.jpg

Dashboard



1773054161255-c6cc97606061765c.jpg

Engine



1773054170013-03ef9553994c3da9.jpg

Boot Space



1773054174789-7b3136b1be97604d.jpg

Stepney / Spare Wheel



1773054191907-327feac78557159.jpg

Tyre - Front Left



1773054209394-41d638646b6a9665.jpg

Tyre - Front Right



1773054221906-6668037e5555346a.jpg

Tyre - Rear Left



1773054227023-5731707fd2545cb4.jpg

Tyre - Rear Right



1773054232515-b8aaed5c3d05c633.jpg

Underbody



1773054237496-eaf12639a4afbfa0.jpg

Other Images



1773054241569-adc3794820c9d5f5.jpg