

Date:	09/03/2026	Customer:	abhihi	Phone:	07414929549
Vehicle:	maruti Innova	Color:	Grey	Year:	2026
Engine No:	SDFSDFSDFSDF	Chassis:	MBJTYK1STA360731	Odometer:	5km

INSPECTION CHECKLIST

BODY EXTERIOR GLASS			
ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES			
ITEM	Y	X	!
Front right tyre			
Front left tyre			
Rear left tyre			
Rear right tyre			
Spare tyre			

INTERIOR & LUGGAGE COMPARTMENT			
ITEM	Y	X	!
Seat mechanism			
Seat belts			
Internal mirrors			
Boot/tailgate lock			

ELECTRICAL CONTROLS			
ITEM	Y	X	!
Ignition lock/starting system			
Battery charging system			
Headlights			
Side lights/running lights			
Rear lights & number plate illumination			
Brake lights			
Indicator & hazard lights			
Reverse & fog lights			
Auxiliary lights			
Panel lights/dashboard illumination			
Switches & controls			
Instrument/controls function			
Horn			
Windows & sunroof operation			
Wipers & jet washers			
Brakes			
Master cylinder security			
Servo/power system			
Flexible hoses			
Pipes/unions & connections			
Discs & pads			
Hand brake operation/adjustments			
Hand brake linkage Pedal/linkage			

ENGINE COMPARTMENT			
ITEM	Y	X	!
Coolant level			
Hoses & pipes			
Drive belts			
Water pump			
Power steering fluid level			
Clutch fluid level		X	
Brake fluid level	Y		
Engine oil level			
Engine mounts			
Turbo/supercharger			
Fuel pump & pipes			
Accelerator linkage			
Cold starting			
Fast idle when engine cold			
Noise level when engine cold			
Excess fumes/smoke			

CLUTCH & TRANSMISSION			
ITEM	Y	X	!
Cables/adjustment			
Hydraulic system			
Linkages (check for signs of wear)			
Casings Mountings			
Drive shaft assemblies			
Universal & sliding joints			
Clutch backlash			
Rubber gaiters Prop-shaft(s)			
Bearings & supports			

EXHAUST SYSTEM			
ITEM	Y	X	!
Inlet manifold			
Outlet manifold Pipes Silencer(s)			
Heat shields & mountings			
Joints & couplings			
Catalytic converter			
Overall system condition			

FUEL SYSTEM			
ITEM	Y	X	!
Fuel tank			
Fuel tank fixings			
Fuel lines			
Breather pipes			

SUSPENSION, UNDERFRAME & STEERING			
ITEM	Y	X	!
Steering joints & ball joints			
Chassis members			
Power steering			
Wheels, hubs & bearings			
Springs & suspension unit			
Pipes & hoses			
Dampers & bushes Gaiters			
Sub frames & mountings			
Suspension arms, mountings & fixings			
Tie bars & anti-roll bars			
Anti roll-bar			
Evidence of floor/chassis corrosion			
Bumper stops & gaiters			


ROAD TEST			
ITEM	Y	X	!
Engine - performance			
Engine - noise			
Engine - excessive fumes or smoke			
Evidence of overheating			
Gearbox operation & noise level			
Final drive operation & noise level			
Clutch operation			
Cooling fan operation			
Instruments & controls functioning			

GENERAL STEERING & HANDLING			
ITEM	Y	X	!
Footbrake operation			
Hand brake operation			
Suspension noise			
Road holding stability			


CONVENIENCE			
ITEM	Y	X	!
Warning lights			
Owners manual			
Service book & history			
Keys & remote controls			

LEAKAGE INSPECTION	
Brake Fluid Leakage	NOT FOUND
Engine Oil Leakage	FOUND
Engine Underside Leak	FOUND
Fuel Leakage	FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND

TOP VIEW



SIDE VIEW




INTERIOR VIEW

VEHICLE INSPECTION CHECKLIST



BOOT VIEW



IDENTIFIED DAMAGES

1. S (scratch) on top view - No description
2. S (scratch) on top view - No description

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

abhii

VEHICLE IMAGES — maruti Innova

Front View



1773055337479-1e3fcab4550f130b.jpg