

Date:	14/05/2026	Customer:	Kshitiz kumar	Phone:	9805328201
Vehicle:	SKODA KYLAQ	Color:	WHITE	Year:	2026
Engine No:	025701	Chassis:	25701	Odometer:	8

INSPECTION CHECKLIST

BODY EXTERIOR GLASS			
ITEM	Y	X	!
Door locks/operation	Y		
Fuel filler cover/petrol cap	Y		
General bodywork condition	Y		
Corrosion	Y		

WHEELS & TYRES			
ITEM	Y	X	!
Front right tyre	Y		
Front left tyre	Y		
Rear left tyre	Y		
Rear right tyre	Y		
Spare tyre	Y		

INTERIOR & LUGGAGE COMPARTMENT			
ITEM	Y	X	!
Seat mechanism	Y		
Seat belts	Y		
Internal mirrors	Y		
Boot/tailgate lock	Y		

ELECTRICAL CONTROLS			
ITEM	Y	X	!
Ignition lock/starting system	Y		
Battery charging system	Y		
Headlights	Y		
Side lights/running lights	Y		
Rear lights & number plate illumination	Y		
Brake lights	Y		
Indicator & hazard lights	Y		
Reverse & fog lights	Y		
Auxiliary lights	Y		
Panel lights/dashboard illumination	Y		
Switches & controls	Y		
Instrument/controls function	Y		
Horn	Y		
Windows & sunroof operation	Y		
Wipers & jet washers	Y		
Brakes	Y		
Master cylinder security	Y		
Servo/power system	Y		
Flexible hoses	Y		
Pipes/unions & connections	Y		
Discs & pads	Y		
Hand brake operation/adjustments	Y		
Hand brake linkage Pedal/linkage	Y		

ENGINE COMPARTMENT			
ITEM	Y	X	!
Coolant level	Y		
Hoses & pipes	Y		
Drive belts	Y		
Water pump	Y		
Power steering fluid level	Y		
Clutch fluid level	Y		
Brake fluid level	Y		
Engine oil level	Y		
Engine mounts	Y		
Turbo/supercharger	Y		
Fuel pump & pipes	Y		
Accelerator linkage	Y		
Cold starting	Y		
Fast idle when engine cold	Y		
Noise level when engine cold	Y		
Excess fumes/smoke	Y		

CLUTCH & TRANSMISSION			
ITEM	Y	X	!
Cables/adjustment	Y		
Hydraulic system	Y		
Linkages (check for signs of wear)	Y		
Casings Mountings	Y		
Drive shaft assemblies	Y		
Universal & sliding joints	Y		
Clutch backlash	Y		
Rubber gaiters Prop-shaft(s)	Y		
Bearings & supports	Y		

EXHAUST SYSTEM			
ITEM	Y	X	!
Inlet manifold	Y		
Outlet manifold Pipes Silencer(s)	Y		
Heat shields & mountings	Y		
Joints & couplings	Y		
Catalytic converter	Y		
Overall system condition	Y		

FUEL SYSTEM			
ITEM	Y	X	!
Fuel tank	Y		
Fuel tank fixings	Y		
Fuel lines	Y		
Breather pipes	Y		

SUSPENSION, UNDERFRAME & STEERING			
ITEM	Y	X	!
Steering joints & ball joints	Y		
Chassis members	Y		
Power steering	Y		
Wheels, hubs & bearings	Y		
Springs & suspension unit	Y		
Pipes & hoses	Y		
Dampers & bushes Gaiters	Y		
Sub frames & mountings	Y		
Suspension arms, mountings & fixings	Y		
Tie bars & anti-roll bars	Y		
Anti roll-bar	Y		
Evidence of floor/chassis corrosion	Y		
Bumper stops & gaiters	Y		


ROAD TEST			
ITEM	Y	X	!
Engine - performance	Y		
Engine - noise	Y		
Engine - excessive fumes or smoke	Y		
Evidence of overheating	Y		
Gearbox operation & noise level	Y		
Final drive operation & noise level	Y		
Clutch operation	Y		
Cooling fan operation	Y		
Instruments & controls functioning	Y		

GENERAL STEERING & HANDLING			
ITEM	Y	X	!
Footbrake operation	Y		
Hand brake operation	Y		
Suspension noise	Y		
Road holding stability	Y		


CONVENIENCE			
ITEM	Y	X	!
Warning lights	Y		
Owners manual	Y		
Service book & history	Y		
Keys & remote controls	Y		

LEAKAGE INSPECTION	
Brake Fluid Leakage	NOT FOUND
Coolant Leakage	NOT FOUND
Engine Oil Leakage	NOT FOUND
Engine Underside Leak	NOT FOUND
External Engine Leak	NOT FOUND
Fuel Leakage	NOT FOUND
Power Steering Fluid Leakage	NOT FOUND
Transmission Fluid Leakage	NOT FOUND

TOP VIEW



SIDE VIEW




INTERIOR VIEW

VEHICLE INSPECTION CHECKLIST



BOOT VIEW



No damages marked.

RECOMMENDATIONS & NOTES

"Congratulations to Mr. Kshitiz Kumar on the delivery of the all-new Skoda Kylaq!
Wishing you endless adventures, safe journeys, and premium driving experiences ahead. ₹~
Proudly inspected and verified by Detailing Garage with professional PDI standards before delivery."

CUSTOMER SATISFACTION REPORT

~~Pre~~-Delivery Inspection (PDI) Successfully Completed

Customer Details

~~C~~ustomer Name: Mr. Kshitiz Kumar

Vehicle Details

~~V~~ehicle Make: Skoda

~~V~~ehicle Model: Skoda Kylaq

Inspection Location

~~M~~andi, Himachal Pradesh

Dealership

Dev Bhoomi Skoda

Professional PDI Inspection Summary

Full Vehicle Diagnostics Performed with Professional Scanner
Vehicle Found in Factory Transport Mode During Initial Scan
Transport Mode Status Verified Successfully
No Permanent Fault Codes Found
Underbody Inspection Completed on Hydraulic Lift
Electrical & ECU Systems Checked
Battery & Charging Parameters Verified
Vehicle Condition Found Genuine & Satisfactory
Dealership Staff Fully Cooperative During Inspection

Technical Observation

During the diagnostic inspection, the vehicle was detected in Factory Transport Mode, which is a normal condition in newly manufactured vehicles before customer delivery.

Transport Mode Indicates:

Vehicle is newly dispatched from manufacturer
Battery-saving factory settings are active
Electronic modules are protected during transportation

No abnormal mechanical or electrical issue detected.
Vehicle health status found satisfactory during inspection.

Customer Satisfaction Note

"We are pleased to confirm that the vehicle was professionally inspected by Detailing Garage and found in genuine factory condition. The transport mode status confirms fresh dispatch condition from manufacturer/dealership logistics."

Inspection Performed By

PDI Done By: Detailing Garage Mandi

Professional Inspection Includes

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

Ritchie

KSHITIZ

Kshitiz kumar

VEHICLE IMAGES — SKODA KYLAQ

Interior



1778764797988-a3233d0e0d6f735e.jpg

Dashboard




1778764836530-fcb717dc281c7220.jpg

Boot Space



1778764940475-99abf209f149a70c.jpg

Stepney / Spare Wheel



1778764992041-896e66e35cd93c5c.jpg

Tyre - Front Right



1778765038071-5a380ade1bd9a86f.jpg

Tyre - Rear Left



1778765060320-3fbee0b1852acf43.jpg

Tyre - Rear Right



1778765073600-37b81cf06c8c572c.jpg

Underbody



1778765138923-ded671673d289012.jpg

Engine



1778766252398-601e1b31953ff73e.jpg

Front View



1778766866938-1c5b74cbe575500.jpg

Rear View



1778766884522-7dc5d71963e30876.jpg

Left Side View



1778766894164-891062ffaf345b95.jpg

Left Side View



1778766905737-b1496518ca9a36e6.jpg

Right Side View



1778766970967-be0edd6a9110a471.jpg

Right Side View



1778766979714-76b2d9f583dbcb48.jpg

Tyre - Front Left



1778767026358-7c653ed7bc0253fb.jpg

Other Images



Other Images



EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US:     

MAIL : info@detailinggarage.in

DETAILING GARAGE™
DETAILING THAT DEFINES LUXURY

INFO LINE : +91-86798-00074 / +91-98160-36880