

|            |                                        |           |                     |           |            |
|------------|----------------------------------------|-----------|---------------------|-----------|------------|
| Date:      | 26/05/2026                             | Customer: | Shammi Sharma       | Phone:    | 9210940608 |
| Vehicle:   | Tata Motors Tata Safari Smart / Safari | Color:    | Frost White / White | Year:     | 2024       |
| Engine No: | 000000                                 | Chassis:  | MAT631930TWD18987   | Odometer: | 91         |

### INSPECTION CHECKLIST

| BODY EXTERIOR GLASS          |   |   |   |
|------------------------------|---|---|---|
| ITEM                         | Y | X | ! |
| Door locks/operation         | Y |   |   |
| Fuel filler cover/petrol cap | Y |   |   |
| General bodywork condition   | Y |   |   |
| Corrosion                    | Y |   |   |

| WHEELS & TYRES   |   |   |   |
|------------------|---|---|---|
| ITEM             | Y | X | ! |
| Front right tyre | Y |   |   |
| Front left tyre  | Y |   |   |
| Rear left tyre   | Y |   |   |
| Rear right tyre  | Y |   |   |
| Spare tyre       | Y |   |   |

| INTERIOR & LUGGAGE COMPARTMENT |   |   |   |
|--------------------------------|---|---|---|
| ITEM                           | Y | X | ! |
| Seat mechanism                 | Y |   |   |
| Seat belts                     | Y |   |   |
| Internal mirrors               | Y |   |   |
| Boot/tailgate lock             | Y |   |   |

| ELECTRICAL CONTROLS                     |   |   |   |
|-----------------------------------------|---|---|---|
| ITEM                                    | Y | X | ! |
| Ignition lock/starting system           | Y |   |   |
| Battery charging system                 | Y |   |   |
| Headlights                              | Y |   |   |
| Side lights/running lights              | Y |   |   |
| Rear lights & number plate illumination | Y |   |   |
| Brake lights                            | Y |   |   |
| Indicator & hazard lights               | Y |   |   |
| Reverse & fog lights                    | Y |   |   |
| Auxiliary lights                        | Y |   |   |
| Panel lights/dashboard illumination     | Y |   |   |
| Switches & controls                     | Y |   |   |
| Instrument/controls function            | Y |   |   |
| Horn                                    | Y |   |   |
| Windows & sunroof operation             | Y |   |   |
| Wipers & jet washers                    | Y |   |   |
| Brakes                                  | Y |   |   |
| Master cylinder security                | Y |   |   |
| Servo/power system                      | Y |   |   |
| Flexible hoses                          | Y |   |   |
| Pipes/unions & connections              | Y |   |   |
| Discs & pads                            | Y |   |   |
| Hand brake operation/adjustments        | Y |   |   |
| Hand brake linkage Pedal/linkage        | Y |   |   |

| ENGINE COMPARTMENT           |   |   |   |
|------------------------------|---|---|---|
| ITEM                         | Y | X | ! |
| Coolant level                | Y |   |   |
| Hoses & pipes                | Y |   |   |
| Drive belts                  | Y |   |   |
| Water pump                   | Y |   |   |
| Power steering fluid level   | Y |   |   |
| Clutch fluid level           | Y |   |   |
| Brake fluid level            | Y |   |   |
| Engine oil level             | Y |   |   |
| Engine mounts                | Y |   |   |
| Turbo/supercharger           | Y |   |   |
| Fuel pump & pipes            | Y |   |   |
| Accelerator linkage          | Y |   |   |
| Cold starting                | Y |   |   |
| Fast idle when engine cold   | Y |   |   |
| Noise level when engine cold | Y |   |   |
| Excess fumes/smoke           | Y |   |   |

| CLUTCH & TRANSMISSION              |   |   |   |
|------------------------------------|---|---|---|
| ITEM                               | Y | X | ! |
| Cables/adjustment                  | Y |   |   |
| Hydraulic system                   | Y |   |   |
| Linkages (check for signs of wear) | Y |   |   |
| Casings Mountings                  | Y |   |   |
| Drive shaft assemblies             | Y |   |   |
| Universal & sliding joints         | Y |   |   |
| Clutch backlash                    | Y |   |   |
| Rubber gaiters Prop-shaft(s)       | Y |   |   |
| Bearings & supports                | Y |   |   |

| EXHAUST SYSTEM                    |   |   |   |
|-----------------------------------|---|---|---|
| ITEM                              | Y | X | ! |
| Inlet manifold                    | Y |   |   |
| Outlet manifold Pipes Silencer(s) | Y |   |   |
| Heat shields & mountings          | Y |   |   |
| Joints & couplings                | Y |   |   |
| Catalytic converter               | Y |   |   |
| Overall system condition          | Y |   |   |

| FUEL SYSTEM       |   |   |   |
|-------------------|---|---|---|
| ITEM              | Y | X | ! |
| Fuel tank         | Y |   |   |
| Fuel tank fixings | Y |   |   |
| Fuel lines        | Y |   |   |
| Breather pipes    | Y |   |   |

| SUSPENSION, UNDERFRAME & STEERING    |   |   |   |
|--------------------------------------|---|---|---|
| ITEM                                 | Y | X | ! |
| Steering joints & ball joints        | Y |   |   |
| Chassis members                      | Y |   |   |
| Power steering                       | Y |   |   |
| Wheels, hubs & bearings              | Y |   |   |
| Springs & suspension unit            | Y |   |   |
| Pipes & hoses                        | Y |   |   |
| Dampers & bushes Gaiters             | Y |   |   |
| Sub frames & mountings               | Y |   |   |
| Suspension arms, mountings & fixings | Y |   |   |
| Tie bars & anti-roll bars            | Y |   |   |
| Anti roll-bar                        | Y |   |   |
| Evidence of floor/chassis corrosion  | Y |   |   |
| Bumper stops & gaiters               | Y |   |   |


| ROAD TEST                           |   |   |   |
|-------------------------------------|---|---|---|
| ITEM                                | Y | X | ! |
| Engine - performance                | Y |   |   |
| Engine - noise                      | Y |   |   |
| Engine - excessive fumes or smoke   | Y |   |   |
| Evidence of overheating             | Y |   |   |
| Gearbox operation & noise level     | Y |   |   |
| Final drive operation & noise level | Y |   |   |
| Clutch operation                    | Y |   |   |
| Cooling fan operation               | Y |   |   |
| Instruments & controls functioning  | Y |   |   |

| GENERAL STEERING & HANDLING |   |   |   |
|-----------------------------|---|---|---|
| ITEM                        | Y | X | ! |
| Footbrake operation         | Y |   |   |
| Hand brake operation        | Y |   |   |
| Suspension noise            | Y |   |   |
| Road holding stability      | Y |   |   |

| CONVENIENCE            |   |   |   |
|------------------------|---|---|---|
| ITEM                   | Y | X | ! |
| Warning lights         | Y |   |   |
| Owners manual          | Y |   |   |
| Service book & history | Y |   |   |
| Keys & remote controls | Y |   |   |

| LEAKAGE INSPECTION           |           |
|------------------------------|-----------|
| Brake Fluid Leakage          | NOT FOUND |
| Coolant Leakage              | NOT FOUND |
| Engine Oil Leakage           | NOT FOUND |
| Engine Underside Leak        | NOT FOUND |
| External Engine Leak         | NOT FOUND |
| Fuel Leakage                 | NOT FOUND |
| Power Steering Fluid Leakage | NOT FOUND |
| Transmission Fluid Leakage   | NOT FOUND |

**TOP VIEW**



**SIDE VIEW**




**INTERIOR VIEW**

VEHICLE INSPECTION CHECKLIST



**BOOT VIEW**



No damages marked.

**RECOMMENDATIONS & NOTES**

Another Happy Customer from Kangra!

Detailing Garage successfully completed a Professional Pre-Delivery Inspection (PDI) for the all-new Tata Safari Diesel 2026 at JKR Motor Palampur.

Customer: Mr. Shammi Sharma  
Vehicle: Tata Safari Diesel 2026  
Dealership: JKR Motor Palampur

Our Professional Inspection Included:  
100+ Detailed Checkpoints  
Full Vehicle Diagnostics with Professional Scanner  
Paint Thickness Inspection using Paint Gauge  
Tyre Inspection using Tyre Gauge  
Complete Underbody Inspection  
Mechanical & Electrical Verification

Result: No Fault Codes Found — Vehicle Delivered in Excellent Condition!

Special thanks to JKR Motor Palampur staff for their cooperation and support.

PDI Done By: Ritchie

Don't take delivery of your new car without a Professional PDI Inspection.

Contact Us:  
+91-8679400014  
+91-8679800074

info@detailinggarage.in  
www.detailinggarage.in

#TataSafari #TataSafari2026 #SafariDiesel #TataMotors #DetailingGarage #ProfessionalPDI #CarInspection #NewCarDelivery #Kangra #Palampur #JKRMotor #CarScanner #PaintGauge #TyreInspection #UnderbodyInspection #CarCare #Automobile #PDIExperts #LuxurySUV #CustomerSatisfaction #DriveSafe #Ritchi

VEHICLE INSPECTED BY (SIGNATURE):

CUSTOMER SIGNATURE:

CUSTOMER NAME:

Shammi Sharma

**DETAILING GARAGE**<sup>TM</sup>  
DETAILING THAT DEFINES LUXURY

INFO LINE : +91-86798-00074 / +91-98160-36880

EXPERIENCE TRUE CAR LUXURY WITH OUR DETAILING SERVICES

FOLLOW US :     

MAIL : INFO@DETAILINGGARAGE.IN



### VEHICLE IMAGES — Tata Motors Tata Safari Smart / Safari

Front View



1779777071555-f56614959c232906.jpg

Rear View



1779777281020-bdcdd8472fea2e3.jpg

Left Side View



1779777293939-6f2cabcd2a54f2ed.jpg

Right Side View



1779777337640-f38e9fabb5021227.jpg

Interior



1779777345171-e3bc4bad095781c5.jpg

Dashboard



1779777355497-6b57f9cea3f93c0f.jpg

Engine




1779777365525-d39d5a5cce4ab0ec.jpg

Boot Space



1779777374298-5ea9fd37d9c5d615.jpg

Tyre - Front Left



1779777412241-fd0076a2b5e5b90a.jpg

Tyre - Front Right



1779777417936-f95d6c4f41077fe2.jpg

Tyre - Rear Left



1779777425163-d8fdffbdaf56c77ea.jpg

Tyre - Rear Right



1779777433749-e000a2f7104336f4.jpg

Underbody



1779777483143-b14f38e8f69c6578.jpg