AUTONOMOUS POTHOLE INTELLIGENCE

Public Works Department (PWD) - Grievance Ticket

Ticket ID: CG-PWD-E4984501

Date Generated: 2026-10-10 10:07:12

Reported By: Autonomous AI Drone/Dashcam System

Hazard Details

Severity Level: HIGH

Latitude: 21.160038640817053

Longitude: 81.78084354891637

Requested Action:

This surface defect has been automatically classified as a risk to road safety. Please dispatch an inspection/repair team to the coordinated location.