

DOKUMEN KENDARAAN - B 1234 TEST

BU: TEST_BU | LOKASI: TEST_LOC

STNK




PAJAK

[Tidak ada gambar]


KIR

[Tidak ada gambar]


FISIK KENDARAAN - B 1234 TEST




Tampak Depan



Tampak Belakang



Samping Kanan



Samping Kiri

DOKUMEN KENDARAAN - D 5678 DEMO

BU: TEST_BU | LOKASI: TEST_LOC

STNK

[Tidak ada gambar]


PAJAK



KIR


[Tidak ada gambar]

FISIK KENDARAAN - D 5678 DEMO




[No Image]

Tampak Depan




[No Image]

Tampak Belakang



[No Image]

Samping Kanan



[No Image]

Samping Kiri

RINGKASAN STATUS ASET

No	Nopol	BU	Status	Keterangan
1	B 1234 TEST	TEST_BU	KURANG (4)	PAJAK, KIR, Samping Kanan, Samping Kiri
2	D 5678 DEMO	TEST_BU	KURANG (5)	STNK, KIR, Tampak Depan, Tampak Belakang, Samping