

Vehicle Inspection Report

USED VEHICLE INSPECTION REPORT

Vehicle:

2019 Example Sedan

Mileage:

68,500 km

Engine:

Engine starts normally.

No visible oil leakage observed.

Transmission:

Transmission shifts normally during inspection.

Brakes:

Front brake pads approximately 40% remaining.

Tyres:

Front tyres approximately 30% remaining.

Rear tyres approximately 50% remaining.

Body:

Minor scratches on rear bumper.

Engine warning light:

No warning light observed during inspection.

Recommendation:

Vehicle should undergo a professional diagnostic scan before purchase.