

Vehicle Inspection Report

Driver: Roland Manders

Vehicle Reg: BJ19 SCV

Defect Number: 576179

Date & Time: 27/08/2025 15:01

Defects: 1


Adblue Level: 1/2

Fuel Level: 1/2

Oil Level: Full

S/N	Defect
1	Seat, seatbelts and cab interior

Vehicle Media



Driver Signature

A handwritten signature consisting of a single, fluid, dark blue ink stroke. The stroke starts at the bottom left, curves upwards and to the right, then descends and loops back towards the left, ending with a small vertical tick mark.