

Apartment Condition Report: Niinitie 46 C 26

 **Online:** <https://beauterre.github.io/Niinitie46C-26/>

 **PDF:** <https://beauterre.github.io/Niinitie46C-26/converted-document.pdf>


(created using: <https://markdowntoword.io/tools/markdown-to-pdf>)

Documents

 **draft:** <https://beauterre.github.io/Niinitie46C-26/NLA-NT46C26-JensHjalmarSnoep-RentalAgreement-17Jul26.pdf>

 **contract:** <https://beauterre.github.io/Niinitie46C-26/NLA-NT46C26-JensHjalmarSnoep-RentalAgreement-19Jul26.pdf>

Layout



Video (youtube)

Room	Link	Timestamp
 Bathroom	View Video 	2026-07-22
 Hallway	View Video 	2026-07-22

 Living Room	View Video 	2026-07-22
 Kitchen	View Video 	2026-07-22
 Bedroom	View Video 	2026-07-22

Legal Framework

This report is maintained in accordance with the **Finnish Law of Accommodation (481/95)**.

According to the law, the tenant is responsible for the care of the apartment. By documenting the pre-existing condition and defects at the start of the lease, this record serves as evidence to distinguish between **pre-existing defects** and **damage caused by the tenant** during the tenancy, ensuring a fair assessment of the security deposit upon move-out.

Evidentiary Standards for issues:

To ensure the authenticity of this report, all documentation relies on four independent timestamping methods:

1. **EXIF Metadata:** All photographs contain original embedded EXIF data (date/time/location), providing an immutable record of when the image was captured.
2. **Version Control:** This repository uses GitHub's Git history, which provides a cryptographically signed timestamp of when each entry and photo was committed to the record.
3. the filenames contain a timestamp. files are uploaded directly from camera.
4. videos are too large to commit to github, placed on youtube with unalterable timestamping.

Move-in Date: 21-07-2026

Tenant: Jens Hjalmar Snoep

Overview

This document serves as a formal, ongoing record of the condition of the apartment. It is designed to track the state of the premises over the duration of the lease to ensure a fair and transparent move-out process.

Verification: To ensure the integrity of the timestamps, all entries and modifications are tracked via GitHub's version control (Git commit history), providing an immutable record of when each issue was first identified.

Note to Landlord: The items listed here are documented for record-keeping purposes. Unless explicitly marked as "Action Required," the tenant is comfortable with the current state and is not requesting immediate repair.

Communication Workflow

This repository is a **historical archive**, not a maintenance request system. For active issues requiring attention, the following escalation path is used:

1. **Initial Report:** WhatsApp message to the *Talomies* (Building Manager), Eero Sahakorpi (+358 45 1594421).
 2. **Follow-up:** WhatsApp message to the Landlord (if unresolved), Mauri Fabric(+358 40 5505149).
 3. **Formal Notice:** Email to the Landlord (for documentation and legal requirements). (Mauri Kangas mauri.kangas@outlook.com)
 4. **Archiving:** Once a report is made via the above channels, it is logged here in this repository for future reference.
-

Defect Log

Item	Location	Date Found	Description of Issue	Photo Reference	Status
Fridge	Kitchen	2026-07-21	[Door handle loose / Not cooling properly]		Documented
Window Filters	kitchen, living room, bedroom	2026-07-21	Mosquito filters are torn/missing		Documented
Ceiling Lamps	kitchen, living room, bedroom, hall, toilet	2026-07-21	Non-functional / no fixture / no bulb		Documented

Kitchen Lamp	Kitchen	2026-07-21	Built-in lamp above stove not working (flickers on/off)		Documented
Bathroom Sink	Bathroom	2026-07-21	Sink is coming off wall, hanging crooked		Documented
Bathroom Shelf	Bathroom	2026-07-21	Toothpaste/accessory shelf is crooked		Documented



Photos

All photos are timestamped and stored in the `/photos` directory of this repository. For a visual gallery, please visit the [Online Version](#).

Preview	Date	Filename	Description
View Image	2026-07-22	IMG20260722081834.jpg	kitchen window
View Image	2026-07-22	IMG20260722081841.jpg	bedroom window
View Image	2026-07-22	IMG20260722081857.jpg	living room window (missing filter)
View Image	2026-07-22	IMG20260722081902.jpg	living room lamp hook, no lamp
View Image	2026-07-22	IMG20260722081910.jpg	hallway lamp, no bulb (fuzzy, will add better image later)
View Image	2026-07-22	IMG20260722081931.jpg	many stains on ceiling
View Image	2026-07-22	IMG20260722081949.jpg	fridge, power light on, cooling and warning light not, fridge is room temperature

View Image 	2026-07-22	IMG20260722081957 . jpg	fridge door handle taped on
View Image 	2026-07-22	IMG20260722082014 . jpg	kitchen light above stove flickering
View Image 	2026-07-22	IMG20260722082055 . jpg	No thermostat found in apartment, radiator thermostat was on full (6), yet normal temperature.
View Image 	2026-07-22	IMG20260722082126 . jpg	sink in bathroom loose and crooked, kit almost loose.
View Image 	2026-07-22	IMG20260722082131 . jpg	toothbrush ledge too crooked and loose to put toothbrush on
View Image 	2026-07-22	IMG20260722082143 . jpg	air freshner (empty) glued to bathroom tiles
View Image 	2026-07-22	IMG20260722082153 . jpg	screw in bathroom tiles
View Image 	2026-07-22	IMG20260722082155 . jpg	holes in bathroom tiles
View Image 	2026-07-22	IMG20260722082215 . jpg	screw bedroom wall
View Image 	2026-07-22	IMG20260722082224 . jpg	two screwholes bedroom wall
View Image 	2026-07-22	IMG20260722082229 . jpg	hook in ceiling bedroom
View Image 	2026-07-22	IMG20260722082241 . jpg	kitchen, sticker with hook
View Image 	2026-07-22	IMG20260722082247 . jpg	floor living room
View Image 	2026-07-22	IMG20260722082257 . jpg	window living room

View Image 	2026-07-22	IMG20260722082306 . jpg	ceiling living room
View Image 	2026-07-22	IMG20260722082314 . jpg	stains on floor living room
View Image 	2026-07-22	IMG20260722082320 . jpg	stain on floor living room
View Image 	2026-07-22	IMG20260722082324 . jpg	stain on floor living room
View Image 	2026-07-22	IMG20260722082340 . jpg	drag trails floor hallway
View Image 	2026-07-22	IMG20260722082350 . jpg	fuzzy, will retake
View Image 	2026-07-22	IMG20260722082352 . jpg	hallway floor
View Image 	2026-07-22	IMG20260722082403 . jpg	stains on closets bedroom
View Image 	2026-07-22	IMG20260722082418 . jpg	stains on closets bedroom
View Image 	2026-07-22	IMG20260722082435 . jpg	broken corner kitchen
View Image 	2026-07-22	IMG20260722082442 . jpg	broken corner kitchen
View Image 	2026-07-22	IMG20260722092339 . jpg	kitchen floor and cabinets
View Image 	2026-07-22	IMG20260722092444 . jpg	hallway closet
View Image 	2026-07-22	IMG20260722092454 . jpg	hallway floor

View Image 	2026-07-22	IMG20260722092457 . jpg	hallway floor
View Image 	2026-07-22	IMG20260722092513 . jpg	bedroom, behind door (synth resting against cabinets)
View Image 	2026-07-22	IMG20260722092522 . jpg	bedroom floor scuffs
View Image 	2026-07-22	IMG20260722092527 . jpg	bedroom floor scuffs
View Image 	2026-07-22	IMG20260722092543 . jpg	bedroom wall behind door to kitchen
View Image 	2026-07-22	IMG20260722092552 . jpg	nail in bedroom window pane
View Image 	2026-07-22	IMG20260722092610 . jpg	kitchen floor small hole
View Image 	2026-07-22	IMG20260722092621 . jpg	kitchen doorway to living room
View Image 	2026-07-22	IMG20260722092639 . jpg	window paint gone living room
View Image 	2026-07-22	IMG20260722092648 . jpg	window living room
View Image 	2026-07-22	IMG20260722092656 . jpg	window living room
View Image 	2026-07-22	IMG20260722092703 . jpg	wall next to window living room
View Image 	2026-07-22	IMG20260722092710 . jpg	living room ceiling
View Image 	2026-07-22	IMG20260722092717 . jpg	living room ceiling

View Image 	2026-07-22	IMG20260722092744 . jpg	living room door to hall
View Image 	2026-07-22	IMG20260722092800 . jpg	hallway outside door
View Image 	2026-07-22	IMG20260722092810 . jpg	hallway outside door
View Image 	2026-07-22	IMG20260722092814 . jpg	hallway outside door
View Image 	2026-07-22	IMG20260722092824 . jpg	hallway outside door
View Image 	2026-07-22	IMG20260722092834 . jpg	inner doorframe hallway
View Image 	2026-07-22	IMG20260722092855 . jpg	stains outer door
View Image 	2026-07-22	IMG20260722092901 . jpg	scuffs outer door
View Image 	2026-07-22	IMG20260722092958 . jpg	door to bedroom/hall
View Image 	2026-07-22	IMG20260722093012 . jpg	door bedroom / kitchen
View Image 	2026-07-22	IMG20260722093032 . jpg	kitchen wall next to window
View Image 	2026-07-22	IMG20260722093038 . jpg	kitchen window
View Image 	2026-07-22	IMG20260722093046 . jpg	kitchen window paint
View Image 	2026-07-22	IMG20260722093057 . jpg	kitchen fridge closet

View Image 	2026-07-22	IMG20260722093113.jpg	kitchen closet next to sink (stain)
View Image 	2026-07-22	IMG20260722093122.jpg	holes kitchen/living doorframe
View Image 	2026-07-22	IMG20260722093126.jpg	holes kitchen/living doorframe
View Image 	2026-07-22	IMG20260722093136.jpg	missing door kitchen/living
View Image 	2026-07-22	IMG20260722101116.jpg	hook sticker hallway
View Image 	2026-07-22	IMG20260722101418.jpg	toilet right after flush



Additional Notes

- Because there are so many small defects, the photos are also a general idea of the state of walls, floors and ceilings, paint job, rust.
- for each room a video has been shot and uploaded (unlisted) onto youtube.
- there is no noticeable mold in bathroom.. there was a foul odour (sewer) when I came in.. It is less noticeable, now the windows have been open a while. I didn't notice the smell when I came in the first time.

Last Updated: 22/07/2026