

Apartment Condition Report: Niinitie 46 C 26

 Online: <https://beauterre.github.io/Niinitie46C-26/>

 PDF: <https://beauterre.github.io/Niinitie46C-26/auto.pdf>

Move-in Date: 21-07-2026

Tenant: Jens Hjalmar Snoep

Layout



Overview

This document serves as a formal record of the condition of the apartment at the start of the lease. The dates of issues added to the document are automatically recorded in GitHub history. The purpose of this list is to document pre-existing damages and defects to ensure they are not attributed to the tenant upon move-out.

Note to Landlord: These items are reported for documentation purposes. Unless otherwise stated, the tenant is comfortable with the current state and is not requesting immediate repair.

Current Defect Log

Item	Location	Date Found	Description of Issue	Photo Reference	Status
Fridge	Kitchen	2026-07-21	[Door handle loose / Not cooling properly]	photos/fridge.jpg following	Documented

Window Filters	kitchen, living room, bedroom	2026-07-21	Mosquito filters are torn/missing	photos/windows.jpg following	Documented
Ceiling Lamps	kitchen, living room, bedroom, hall, toilet	2026-07-21	Non-functional / no fixture / no bulb	photos/lamps_ceiling following	Documented
Kitchen Lamp	Kitchen	2026-07-21	Built-in lamp above stove not working (flickers on/off)	photos/lamp_kitchen.jpg	Documented
Bathroom Sink	Bathroom	2026-07-21	Sink is coming off wall, hanging crooked	photos/sink.jpg	Documented
Bathroom Shelf	Bathroom	2026-07-21	Toothpaste/accessory shelf is crooked	photos/shelf.jpg	Documented



Photo Evidence

All photos are timestamped and stored in the `/photos` directory of this repository.

1. **Fridge:** See `photos/fridge.jpg`
2. **Windows:** See `photos/windows.jpg`
3. **Bathroom:** See `photos/sink.jpg` and `photos/shelf.jpg`



Additional Notes

- [Example: Any scratches on the floor or marks on the walls]
- [Example: Any issues with the locking mechanism of the front door]

Last Updated: [Insert Date]