



Invoice	Date
PSI-001229081	08/31/26

14-AFW
Alliance Fort Worth Corporate
Headquarters
15000 Heritage Parkway
FORT WORTH, TX 76177

USA

Service Invoice

Bill To: **KANNON MANUFACTURING**
C109050 **INC**
DENISE TOLMAN
5129 VESTA FARLEY RD
FORT WORTH, TX 76119
USA

Ship To: **KANNON MANUFACTURING**
C109050 **INC**
DENISE TOLMAN
5129 VESTA FARLEY RD
FORT WORTH, TX 76119
USA

Invoice Date	Salesperson	Work Order No.	Purchase Order No.	Due Date
08/31/26	Chris Cabrera	W1355277		09/30/26
Make	Model	Serial No.	Fleet Code	Meter Reading
CAT	P5000-LP	AT3512274		3,777

Service Requested:	<i>HYD LINE BUSTED</i>
Work Performed:	
Reporting Code:	TRAVPARTS - TRAVELED FOR PARTS.
	HOSE - REMOVED/REPLACED HOSE.

PLEASE REMIT TO:
Shoppa's Material Handling, Ltd
PO Box 612027
Dallas, TX 75261-2027

Materials	430.40
Labor	967.50
Sales Tax	115.33
Total Due	1,513.23

Parts Return Policy

Non-stock parts require a 50% non-refundable deposit prior to order

Items classified non-returnable by our vendor – not acceptable for credit

Parts returned 0-30 days – 25% restocking charge on returnable items

Parts returned over 30 days – special handling subject to vendor's return policy

Minimum parts return - \$25.00 extended value

All returns must be authorized prior to returning parts and must be accompanied by the original packaging and a copy of the original invoice on which the parts were purchased.

Terms of Sale or Lease

Acceptance of delivery of the equipment described hereon shall constitute acceptance by the buyer or lessee of the following terms and conditions upon which said equipment is sold.

Disclaimer of Warranties

The buyer agrees and acknowledges that Shoppas material handling, Ltd ("SMH") makes no warranties express or implied, with respect to the equipment or part sold or leased except such warranty as may have been given to the buyer or lessee in writing by SMH and SMH expressly disclaims any warranty or merchantability or fitness for a particular purpose with respect to such equipment or part.

Disclaimer of Liability

The buyer agrees and acknowledges that SMH disclaims and shall have no liability whatsoever for any damage, loss or injury to a person or property, including any damage, loss or injury attributable to SMH's negligence or fault resulting from or arising out of the manufacture, sale, lease, delivery, installation, repair, operation, failure or use of such equipment or part. In the event that this document pertains to the lease of said equipment, above terms and conditions shall apply to the lessee thereof the following additional terms shall prevail: (a) lessee insurance thereon; (b) the equipment shall at all times remain the property of SMH and shall be returned to it upon expiration of the rental period in the same condition as at the date of delivery, ordinary wear expected.

Terms of Sale for Used Equipment

This being used equipment in the manufacture or production of which we were not involved (this sale is on an "as-is" basis) and all warranties, expressed or implied as to the merchantability or fitness for a particular purpose are expressly negated. All claims for deficiencies must be made within 48 hours after receipt of goods

Toyota Warranty Disclaimer

Certain equipment, parts, accessories or attachments either purchased under this invoice or used during services rendered under this invoice were not manufactured by or on behalf of or specifically sold or approved by Toyota Material Handling, U.S.A., Inc. ("TMHU"). Such equipment, parts, accessories or attachments are not included in any warranties, express or implied, furnished by TMHU or any of TMHU's suppliers.

All past due accounts are subject to a 1 -1/2% finance charge per month



WORK ORDER

WORK ORDER # W1355277
SERVICE VISIT # SV-244551
DATE 8/26/2026

Note: This is a service receipt, not an invoice.

BILL TO CUSTOMER

C109050
KANNON MANUFACTURING INC
5129 VESTA FARLEY RD
FORT WORTH TX, 76119

SHIP TO CUSTOMER

C109050
KANNON MANUFACTURING INC
5129 VESTA FARLEY RD
FORT WORTH TX,
76119

CUST PO

QUOTE #

CONTACT

PHONE #

TECH TORRY

EQUIPMENT #	MAKE	MODEL	SERIAL
E105373	CAT	P5000-LP	AT3512274
CUST UNIT #	Hour Meter		
	3777		

SERVICE DESCRIPTION

HYD LINE BUSTED

REASON FOR SERVICE

UNIT HAD OIL/FLUID LEAK.
Sideshift cylinder hose leaking.

CAUSE / CONDITION

HOSE HAD A PIN HOLE.

REPAIRS MADE

TRAVELED FOR PARTS.REMOVED/REPLACED HOSE.

RECOMMENDATIONS**PARTS / MATERIALS**

QTY	DESCRIPTION
1	Safety Checklist
1	Service Call Ryan De La Torre
1	Sublet
1	BRAKE CLEANER, NON-CHLORINATED 12.5 oz

 8/26/2026

SIGNATURE – eSigned by Ruben Perez

DATE



WORK ORDER

WORK ORDER #

W1355277

SERVICE VISIT #

SV-244551

DATE

8/26/2026

Note: This is a service receipt, not an invoice.

	8/26/2026
---	-----------

SIGNATURE – eSigned by Ruben Perez

DATE

Safety Checklist

Generated: 8/26/2026, 9:05:37 AM

Immediate Action

Any issues regarding the horn?

- Yes

Notes: Horn inop.

Passed

Does the hour meter display work?

- Yes

Are brakes functioning properly?

- Yes

Are all lights functioning as needed?

- Yes

Are there any leaks in system?

- No

Are there any issues with the steering?

- No

Are there any concerns regarding the overhead guard?

- No

Data tag in need of replacement?

- No

Fluid levels adequate? Engine, Trans, Hyd and Coolant?

- Yes

Seatbelt in need of replacing?

- No

Notes: Not equipped with a seat belt.

Parking brake in need of attention?

- No

✓ **Did you offer to show replaced parts to customer?**

- Yes