




Rent Revenue




Rent Income







Administrative Expenses



Office Expenses



Contracts Expense



AJ & J Painting Inc.
INTERIOR - EXTERIOR PAINTING
P.O. BOX 1002
STUDIO CITY, CA 91614
LIG.#: 755502
Fax (818) 763-8992
Phone (818) 406-1025



TODAY'S DATE 2-23-22

4177 INVOICE

| MER'S NAME Long Beach senior Housing. | DUE DATE | DATE |
|--|---------------|---------------------|
| S 575 E VErnon ST | P.O.# | 38407 |
| ong Beach Ca 90806 PHONE# | | |
| JOB DESCRIPTION & REMARKS | | AMOUNT |
| Patch two holes in main electrical room and paint door | | |
| Patch and paint soffit in main electrical room | | |
| Paint all parking garage window grates | | |
| Paint parking garage gate and pedestrian door adjacent | | |
| Patch and paint foam accent to right of parking gate under window grate | 1 | |
| Patch and paint small green stucco at bottom by center patio garage exit | door | |
| Paint 3 center courtyard handrails | | |
| Paint small pipe exiting to right side of Managers window | | |
| Paint fire hose connections at front of building | | |
| Patch and paint entire lower stucco wall behind fire hose connections | (wolding) | |
| Paint alley fence with large gate at end by electrical transformer (after | weiding) | |
| Paint pipe elbow drain in alley left of stair #2 door | | |
| Paint stair # 2 door | | |
| Pressure wash stucco wall under main patio in the alley | | |
| Paint clevator machine room across the manager office Paint main trash room doors and two yellow bollards inside room | | |
| Pressure wash main trash room | | |
| Paint garage exit door, to center courtyard inside and outside door jam | | |
| Paint garage elevator room with door and jam | | |
| Paint garage elevator room with door and jam Paint garage to lobby door | | |
| Patch and paint water damage on wall behind lobby to garage door | | |
| Patch and paint water damage on ceiling in main lobby | | |
| Patch and paint ceiling storage room, located in community room | | |
| Paint all interior small trash rooms (4) | | |
| Third Floor. Repair stucco one wall across the laundry, drywall repair a | and paint one | wall, paint laundry |
| room door and | | |
| Trash room door, paint one wall between apt #312 and 313 paint 3 do | ors on stairw | ay. |
| Roof area. Paint 3 doors 3 fire hose connection and 2 gas line. | | |
| Stair # 2 drywall repair and paint under the door roof | | |
| | | |

Richard Laughlin Plumbing, Inc.

Invoice

Contractors License #985870 11684 Ventura Boulevard, #504 Studio City, California 91604

Phone (818) 761-2205 Fax (818) 761-2308 laughlinplumbing@gmail.com

| Date | Invoice # | | |
|----------|-----------|--|--|
| 6/1/2024 | 36142 | | |

Billing Address

Long Beach Senior Housing mhfpayables@menorahhousing.org 575 E. Vernon St. Long Beach, CA 90806

| Job Address | |
|---------------------------|--|
| Long Beach Senior Housing | |
| 575 E. Vernon St. | |
| Long Beach, CA 90806 | |
| 50 1000 | |

P.O. # 45418 **Service Date** Description Amount 5/30/2024 Perform hydrojetting of sewer vent lines for kitchens from roof vents. 3,600.00 Three technicians on site with MHF maintenance to provide access to units. Perform CCTV inspections of line. Additional jetting done for laundry lines and three sewer main lines. 7/1/2024 Due Date Total

Terms are net 30 from invoice date. Past due balances will incur a finance charge assessed at 5% per year. Any Discounts provided herein are only valid if payment in full is received by the Due Date.

Please include Invoice Number in Memo of Check We do not accept credit cards. Thank you

\$3,600.00

NOTICE: Under the California Mechanics' Lien Law (Section 7018.5 of the California Business and Professions Code), Under the California Mechanics' Lien Law (Section '1018.5 of the California Business and Professions Code), and youthractor, abbeer, supplier, or other person who helps to improve your property, but is not paid for his work or supplies, has a right to place a lien on your property where the work was performed and to say you in court to obtain payment. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sail used to satisfy what you one. This can happen even if you have paid your contractor in full if the contractor's sub-contractors, laborers, or suppliers remain unpaid.

Richard Laughlin Plumbing, Inc.

Invoice

Contractors License #985870 11684 Ventura Boulevard, #504 Studio City, California 91604

Phone (818) 761-2205 Fax (818) 761-2308 laughlinplumbing@gmail.com

| Date | Invoice # | |
|------------|-----------|--|
| 10/21/2023 | 35129 | |

Billing Address

Long Beach Senior Housing mhfpayables@menorahhousing.org 575 E. Vernon St. Long Beach, CA 90806

| Job Address | |
|---------------------------|--|
| Long Beach Senior Housing | |
| 575 E. Vernon St. | |
| Long Beach, CA 90806 | |
| 75 UWA | |

P.O. # 43835 **Service Date** Description Amount 10/5/2023 Perform boiler maintenance and report for (4) four boilers. 700.00 Lower East Boiler. 825.00 Install new hot surface ignition assembly. Install new flowswitch assembly. 10/20/2023 Lower West Boiler 1,630.00 Install new boiler pump and motor. Due Date 11/25/2023 Total

Terms are net 30 from invoice date. Past due balances will incur a finance charge assessed at 5% per year. Any Discounts provided herein are only valid if payment in full is received by the Due Date.

Please include Invoice Number in Memo of Check We do not accept credit cards. Thank you

\$3,155.00

NOTICE: Under the California Mechanics' Lien Law (Section 7018.5 of the California Business and Professions Code), Under the California Mechanics' Lien Law (Section '1018.5 of the California Business and Professions Code), and youthractor, abbeer, supplier, or other person who helps to improve your property, but is not paid for his work or supplies, has a right to place a lien on your property where the work was performed and to say you in court to obtain payment. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sail used to satisfy what you one. This can happen even if you have paid your contractor in full if the contractor's sub-contractors, laborers, or suppliers remain unpaid.

Richard Laughlin Plumbing, Inc.

Invoice

Contractors License #985870 11684 Ventura Boulevard, #504 Studio City, California 91604

Phone (818) 761-2205 Fax (818) 761-2308 laughlinplumbing@gmail.com

| Date | Invoice # | | |
|-----------|-----------|--|--|
| 3/30/2023 | 34479 | | |

Billing Address

Long Beach Senior Housing mhfpayables@menorahhousing.org 575 E. Vernon St. Long Beach, CA 90806

| Job Address | |
|---------------------------|--|
| Long Beach Senior Housing | |
| 575 E. Vernon St. | |
| Long Beach, CA 90806 | |
| 73 UTW | |

P.O. # 43055 **Service Date** Description Amount 3/30/2023 1. Install new 6" cleanout to grade on South main line. 6,780.00 2. Install 4" cleanout to grade with yard box on middle main line. 3. Perform hydrojetting with CCTV assist through (3) exterior North, South and middle cleanouts through to city sewer. 4. Perform hydrojetting of lines consecrating to new 6" line and additional horizontal lines in garage. 9/21/2023 Due Date

Terms are net 30 from invoice date. Past due balances will incur a finance charge assessed at 5% per year. Any Discounts provided herein are only valid if payment in


full is received by the Due Date.

Please include Invoice Number in Memo of Check We do not accept credit cards. Thank you

\$6,780.00

Total

NOTICE: Under the California Mechanics' Lien Law (Section 7018.5 of the California Business and Professions Code), Under the California Mechanics' Lien Law (Section '1018.5 of the California Business and Professions Code), and youthractor, abbeer, supplier, or other person who helps to improve your property, but is not paid for his work or supplies, has a right to place a lien on your property where the work was performed and to say you in court to obtain payment. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sail used to satisfy what you one. This can happen even if you have paid your contractor in full if the contractor's sub-contractors, laborers, or suppliers remain unpaid.



OTHER OPERATING & MAINTENANCE EXPENSE

SIDS A/C, HEATING & REFRIG., INC. 5654 W. PICO BLVD. LOS ANGELES, CA 90019 (323)930-2560 sidsac@sbcglobal.net



INVOICE

BILL TO MENORAH HOUSING FOUNDATION 10991 W PICO BLVD LOS ANGELES, CA 90064 DATE 10/05/2023

DUE DATE 10/25/2023

TERMS NET 20 DAYS

SALES REP RODNEY

| DATE | ACTIVITY | QTY | RATE | AMOUNT |
|--------------|---|------------|----------|----------|
| 10/05/2023 | SUPER BOOSTER STP SUPER BOOST | 1 | 47.30 | 47.30T |
| 10/05/2023 | R-410A FREON | 4 | 76.50 | 306.00T |
| 10/05/2023 | NITROGEN NITROGEN CHARGE | T | 82.86 | 82.86T |
| 10/05/2023 | RECOVERY DRIER RECOVERY DRIER 083 | T | 60.88 | 60.88T |
| 10/05/2023 | HEAT PUMP DRIER 163S HEAT PUMP DRIER | 1 | 188.93 | 188.93T |
| 10/05/2023 | VACUUM VACUUM | 1 | 49.00 | 49.00T |
| 10/05/2023 | WELDING WELDING CHARGE | 1 | 90.91 | 90.91T |
| 10/05/2023 | RECOVERY RECOVERY CHARGE | 1 | 105.00 | 105.00T |
| 10/05/2023 | LABOR LABOR | 6 1 | 1,545.00 | 1,545.00 |
| 575 E VERNON | | SUBTOTAL | | 2,475.88 |
| | | TAY | | 95.42 |

 SUBTOTAL
 2,475.88

 TAX
 95.42

 TOTAL
 2,571.30

 BALANCE DUE
 \$2,571.30

Sincerity Integrity Dependability Satisfaction

S Air Conditioning, Heating & Refrigeration, Inc.





No. 1007.22

Service / Installations / Design Since 1958
Air Conditioning • Heating • Refrigeration
Phone (323) 930-2560 • Fax (323) 930-2542
E-mail: sidsac@sbcglobal.net
5654 W. Pico Blvd. / Los Angeles, California 90019
California State License #717456

| ILL O: | JOB: Long Reach Senior |
|-----------|------------------------|
| | Long Beach, CA |
| | |

| d uni y insi daced. | t ce de ti Reco yre | te de solo | presson | - ent |
|--|------------------------------|---|---|--|
| y insi daced. ced con | de Ja Lecu upre | te de voer | parta ed S r. Un | |
| y insi daced. ced con | de Ja Lecu upre | te de voer | parta ed S r. Un | 20 jeo |
| daced. | Recupre | se o | 1 | rea it |
| | 76 | SO | 1 | 30 |
| | 76 | 50) | 1 | 30 |
| m 17 Mascol | 76 | 5.0 | 1 | 30 |
| m 1717860/V | 76 | 50 | 1 | 30 |
| m 1717860/V | 76 | 50 | 1 | 30 |
| M DUPERIN | M (0 | 50 | 1 | 30 |
| m 10 massolv | 7 (0 | 50 | Commission will be | - |
| M DVPESOV | | 15/16 | 306 | 00 |
| MIDVASSIV | A. | | 82 | 86 |
| | War | anti | IN | V/c |
| 1 | 1 | 1 | ('' | |
| | | | 60 | 88 |
| | | | | 1 |
| | | | 1 | 00 |
| | | | 1 | 91 |
| | | | The second | 000 |
| | YE | S | NO NO | 0 |
| | | | 100 | |
| | | 1000 | and the | 10.2 |
| SALES TAX | 935 | 42 | 1026 | 30 |
| OR MISC. | | | | |
| PREVENTIVE MAINTENANCE AGREEMENT | red C | | | |
| OTAL LABOR | | | 1.545 | 100 |
| 4 | TOTAL | | 571 | 21 |
| | PREVENTIVE MAINTENANCE | EQUIRED EQUIRED MATERIAL & SALES TAX SALES TAX RUCK CHARGE OR MISC. PREVENTIVE MAINTENANCE AGREEMENT OTAL LABOR | EQUIRED MATERIAL & SALES TAX SALES TAX HUCK CHARGE OR MISC. PREVENIVE MAINTENANCE AGREEMENT OTAL LABOR | EQUIRED EQUIRED MATERIAL & SALES TAX RUCK CHARGE OR MISC. PREVENTIVE MAINTENANCE MAINTENANCE AGREEMENT OTAL LABOR J. 545 |

SIDS A/C, HEATING & REFRIG., INC. 5654 W. PICO BLVD. LOS ANGELES, CA 90019 (323)930-2560 sidsac@sbcglobal.net



INVOICE

BILL TO MENORAH HOUSING FOUNDATION 10991 W PICO BLVD LOS ANGELES, CA 90064 DATE 03/22/2024

DUE DATE 04/11/2024

TERMS NET 20 DAYS

1,820.58

\$1,820.58

SALES REP RODNEY

| DATE | ACTIVITY | QTY | RATE | AMOUNT |
|--------------|-----------------------------------|-----------------|--------|----------|
| 03/22/2024 | COIL CLEANING | 1 | 68.00 | 68.00T |
| 03/22/2024 | CC2 | -1 | 71.94 | 71.94T |
| 03/22/2024 | CRANKCASE HEATER 240V, 40WATTS | 1 | 196.65 | 196.65T |
| 03/22/2024 | RX FLUSH ACID SCAV | 1 | 145.53 | 145.53T |
| 03/22/2024 | TEMP SENSOR EVAP TEMP SESNOR | 1 | 79.07 | 79.07T |
| 03/22/2024 | THERM PROGRAMMABLE THERMOSTA | 1 AT - T2800 | 267.00 | 267.00T |
| 03/22/2024 | RX FLUSH FLUSH KIT | 1 | 328.80 | 328.80T |
| 03/22/2024 | LABOR | 1 | 545.00 | 545.00 |
| 575 E VERNON | ST. #209 | SUBTOTAL | | 1,701.99 |
| | | TAX | | 118.59 |

TOTAL

BALANCE DUE

Bhasista Care Commen

Sincerity Integrity Dependability Satisfaction

SIDS Air Conditioning, Heating & Refrigeration, Inc.

BBB



No. 099822

15 / /

Service / Installations / Design Since 1958

Air Conditioning • Heating • Refrigeration

Phone (323) 930-2560 • Fax (323) 930-2542


E-mail: sidsac@sbcglobal.net

5654 W. Pico Blvd. / Los Angeles, California 90019 California State License #717456

BILL Menoral housing toundation JOB: Long Beach St. 1209 Long Beach, At 209 Long Beach, At

PAYMENT TERMS: 10 DAYS FROM DATE OF INVOICE OR 1 1/2% MONTHLY INTEREST DUE QTY. AMOUNT oosino eclion. Temp Sensor 4/10-5 NEW FOLLOW-UP SERVICE REQUIRED PREVIOUSLY MENTIONED FOLLOW-UP SERVICE REQUIRED MATERIAL & SALES TAX X VERIFIES WORK DONE TRUCK CHARGE OR MISC. PREVENTIVE MAINTENANCE AGREEMENT LABOR PER 1st HOUR TOTAL LABOR 545 LABOR Wedns e s PER 2nd HOUR PLEASE PAY FROM INVOICE STATEMENTS ON REQUEST CUSTOMER'S P.O. # TOTAL

PLEASE PRESS FIRMLY - 4 COPIES



Water

35,827.12

Electricity

0.00

UTILITIES EXPENSES

Gas

