















Owner : SHRVAN SIR	25/08/2026
Consultant Company; DefectFinder-Property Inspection services	Floor Number : 2nd
Technical Engineer; Adnan -Civil Engineer	Flat Number : 208
	Proprty for inspection : 2BHK Flat







Snagging Report







S/No.	Description	Photos	Status	Ramarks
1	Number plate to be fix			
2	Door damage,rectify			
3	Threshold joint cleaning , grouting and size			
4	damage architrave			
5	Hinges scratch			
6	Door shutter alignment and clean			
7	Poor finish corner			
8	Corner paint levelling and finish			
9	Clean paint,rectify poor finish around socket			
10	Paint clean and finish			
11	Not alignment			
12	Floor tile clean, level and grouting final finish			






13	Remove protection for smoke dtector and clean			
14	Clean and paint finish around bell			
15	Corner finish around pipe, clean			
16	Clean			
17	Close around gas pipe			
18	Provide proper connection, clean			
19	Washing machine not provided			
20	poor finish grouting rectify and re-grout kitchen sink joint			
21	Freeze, provide proper conection and clean			
22	Clean kitchen cabinets inside and outside			
23	Damage tiles replace and rectify			
24	Corner paint finish			
25	Corner undulation paint poor finish			







26	Poor paint finish			
27	Corner paint poor finish			
28	Ac grill joint ,level and finish ,clean			
29	Crack between wall and board poor finish			
30	Clean floor tiles and kitchen platform,kitchen cabinet inside and out side			
31	Smoke detector clean and finish,remove protection			
32	Corner paint not aligned and poor finish			
33	Poor finish wall paint			
34	Poor finish wall paint,not aligned and level , rectify			
35	Light not provided			
36	Poor finish paint around socket level and alignment			
37	Ceiling paint poor finishing			
38	Poor finish around sprinkler			





39	Undulation corner joint final coat paint			
40	Clean			
41	Floor tiles clean and re-grout			
42	Leak test			
43	Poor finish paint , bewtween joint ceiling and aluminium weather sealnet			
44	Clean and finish corner paint, grouting			
45	common washroom door aligment ,clean and level ,rectify			
46	Poor finish corner			
47	Poor finish grouting			
48	common washroom door alignment			
49	Wall tiles joint poor finish			
50	finish around plate			
51	Damage door shutter rectify			



52	slope check			
53	Clean			
54	Sanitary loose connection			
55	Bathroom door aligment ,clean and level ,rectify			
56	Wall tiles damage ,rectify			
57	Re -grout wall tiles poor finish			
58	Floor clean and tiles joint finish re-grout and slope test			
59	Slope check water should be available			
60	Corner poor finish			
61	Wall tiles damage			
62	Around plate grout finish			
63	paint undulation ceiling			
64	Poor finish access panel			

65	Bedroom door alignment, clean level and finsh			
66	Architrave poor finish			
67	paint damage ,found poor finish ,rectify corner joint			
68	poor finish paint around socket ,level and alignment			
69	Master bathroom door clean,alignment and level			
70	poor finish architrave joint			
71	poor finish architrave joint			
72	poor finish grouting			
73	Floor tiles clean and re-grout			
74	Slope check water is available master bath			
75	poor finish grouting rectify and re-grout			
76	corner grout finish			
77	poor finish grouting			

78	poor finsih grouting			
79	Clean			
80	Sanitary loose connection			
81	Loose connection			
82	poor finish corner			
83	poor finish around plate			
84	Loose connection			
85	Poor finish paint			
	Architrave scratch			
87	Balcony remove scaffloding			
88	Poor finish wall paint balcony			
89	Poor finish wall paint balcony			
90	Poor finish ceiling paint			

91	Light not alignment and clean			
92	Balcony floor tiles clean			
93	Glass clean balcony			
94	slope test			
95	Balcony floor tiles clean ,re-grout			
96	Balcony top channel remove protection for snagging			
97	Poor finish top channel joint			
98	Loose fix top channel ,make proper support and fix glass panel and top channel properly			
99	Poor finish paint			
100	Clean			
101	Poor finish paint			
102	Crack , poor finish paint to be rectify			
103	Ac grill joint ,level and finish ,clean			

104	lean ,level and poor finish around socket,rectif			
105	Poor finish tiles skirting			
106	Poor finish wall paint			
107	poor finish corner paint			
108	Smoke detector clean and finish,remove protection			
109	Light clean			
110	Poor finish wall paint corner			
111	Corner paint not aligned and poor finish			
112	Poor finish wall paint			
113	Poor finish skirting ,clean and re-grout			
114	Floor tiles clean and re-grout			
115	Poor finish corner			
116	Floor tiles damage			

117	Lock not working smooth			
118	Clean			
119	Leak test			
120	Poor finish paint ceiling corner			
121	Poor finish paint corner			
122	Wardrobe clean and alignment			
123	clean			
124	Wardrobe clean inside and out side			
125	Screw visible,rectify			
126	Poor finish corner above skirting			
127	poor finish gap top joint ,rectify	