



- △ Private Tank Tipping
- Shelter Damage
- △ Septic Tank Full
- Camp Facility Damage
- Road Damage

- Muddy Road
- Inaccessible Road
- < 5cm Water
- > 5cm Water

- District Boundaries
- Block Boundaries
- Camp Facilities
- Potential Flow
- Mosque

Data Sources: UNHCR, UNICEF, ACTED, JEN, OXFAM

Satellite Acquisition Date: 30/06/2016 by DigitalGlobe
Provided by: UNOSAT

Projection: WGS 1984 UTM Zone 37N

File: REACH_JOR_Map_Zaatari_WASH_Flood_Damage
_District_Dec2016

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the partners, associates or donors mentioned on this map.