Visual Property Record

Property Name:

Property Address:

Date of Service: 03/19/2026

Time Window: 9:53 AM to 10:26 AM

Weather at service start: Drizzle | 38°F | Wind 6 mph | Precipitation 0.04 in

**Weather conditions may have affected visibility at the time of documentation*

Weather data provided by Open-Meteo.

Report Reference ID: D6C95E9E-04A8-45CD-B996-8DBFDA34EDB2

Prepared by: Example Property Group

Generated with SCOUT software

Report Date: 03/23/2026

Documentation Index

Building 1 West Elevation pages 4-14

BUILDING 1 | WEST | OVERVIEW | ANGLE 1 4

BUILDING 1 | WEST | ELEVATION | ANGLE 1 4

BUILDING 1 | WEST | CLADDING / SIDING | ANGLE 1 5

BUILDING 1 | WEST | DOWNSPOUTS | ANGLE 1 5

⚑ BUILDING 1 | WEST | DOWNSPOUTS | ANGLE 2 6

BUILDING 1 | WEST | ENTRY | ANGLE 1 6

BUILDING 1 | WEST | ENTRY | ANGLE 2 7

⚑ BUILDING 1 | WEST | ENTRY | ANGLE 3 7

BUILDING 1 | WEST | EXTERIOR STAIRS | ANGLE 1 8

⚑ BUILDING 1 | WEST | PORCH | ANGLE 1 8

⚑ BUILDING 1 | WEST | PORCH | ANGLE 2 9

BUILDING 1 | WEST | PORCH | ANGLE 3 9

BUILDING 1 | WEST | ROOFLINE | ANGLE 1 10

⚑ BUILDING 1 | WEST | ROOFLINE | ANGLE 2 10

⚑ BUILDING 1 | WEST | ROOFLINE | ANGLE 3 11

⚑ BUILDING 1 | WEST | ROOFLINE | ANGLE 4 11

⚑ BUILDING 1 | WEST | ROOFLINE | ANGLE 5 12

⚑ BUILDING 1 | WEST | ROOFLINE | ANGLE 6 12

BUILDING 1 | WEST | SIDEWALK | ANGLE 1 13

⚑ BUILDING 1 | WEST | SIDEWALK | ANGLE 2 13

BUILDING 1 | WEST | WINDOW | ANGLE 1 14

Building 1 South Elevation pages 15-20

BUILDING 1 | SOUTH | ELEVATION | ANGLE 1 15

BUILDING 1 | SOUTH | CLADDING / SIDING | ANGLE 1 15

BUILDING 1 | SOUTH | DOWNSPOUTS | ANGLE 1 16

⚑ BUILDING 1 | SOUTH | PORCH | ANGLE 1 16

BUILDING 1 | SOUTH | PORCH | ANGLE 2 17

BUILDING 1 | SOUTH | PORCH | ANGLE 3 17

BUILDING 1 | SOUTH | ROOFLINE | ANGLE 1 18

⚑ BUILDING 1 | SOUTH | ROOFLINE | ANGLE 2 18

BUILDING 1 | SOUTH | ROOFLINE | ANGLE 3 19

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

Documentation Index

BUILDING 1 | SOUTH | SIDEWALK | ANGLE 1 19

⚑ BUILDING 1 | SOUTH | SIDEWALK | ANGLE 2 20

BUILDING 1 | SOUTH | WINDOW | ANGLE 1 20

Building 1 North Elevation pages 21-21

BUILDING 1 | NORTH | DOWNSPOUTS | ANGLE 1 21

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | OVERVIEW | ANGLE 1
March 19, 2026 • 9:53 AM

BUILDING 1 | WEST | ELEVATION | ANGLE 1
March 19, 2026 • 9:53 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | CLADDING / SIDING | ANGLE 1
March 19, 2026 • 10:14 AM

BUILDING 1 | WEST | DOWNSPOUTS | ANGLE 1
March 19, 2026 • 10:09 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | DOWNSPOUTS | ANGLE 2

⚑ Grading at downspout

March 19, 2026 • 10:10 AM

BUILDING 1 | WEST | ENTRY | ANGLE 1

March 19, 2026 • 10:11 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | ENTRY | ANGLE 2
March 19, 2026 • 10:12 AM

BUILDING 1 | WEST | ENTRY | ANGLE 3
⚑ Gaps below door
March 19, 2026 • 10:15 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | EXTERIOR STAIRS | ANGLE 1
March 19, 2026 • 9:56 AM

BUILDING 1 | WEST | PORCH | ANGLE 1
⚑ Ceiling separation
March 19, 2026 • 10:13 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | PORCH | ANGLE 2

⚑ Missing caulking

March 19, 2026 • 10:14 AM

BUILDING 1 | WEST | PORCH | ANGLE 3

March 19, 2026 • 10:16 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | ROOFLINE | ANGLE 1
March 19, 2026 • 9:57 AM

BUILDING 1 | WEST | ROOFLINE | ANGLE 2
⚑ Separation at roof edge
March 19, 2026 • 9:58 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | ROOFLINE | ANGLE 3

⚑ Missing pieces in fascia

March 19, 2026 • 9:59 AM

BUILDING 1 | WEST | ROOFLINE | ANGLE 4

⚑ Bow in porch header

March 19, 2026 • 10:01 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | ROOFLINE | ANGLE 5

⚑ Fascia gaps and separation

March 19, 2026 • 10:16 AM

BUILDING 1 | WEST | ROOFLINE | ANGLE 6

⚑ Fascia separation and bird nest

March 19, 2026 • 10:17 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | SIDEWALK | ANGLE 1
March 19, 2026 • 9:54 AM

BUILDING 1 | WEST | SIDEWALK | ANGLE 2
⚑ Sidewalk low point / grading
March 19, 2026 • 9:55 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | WEST | WINDOW | ANGLE 1
March 19, 2026 • 10:12 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | ELEVATION | ANGLE 1
March 19, 2026 • 10:18 AM

BUILDING 1 | SOUTH | CLADDING / SIDING | ANGLE 1
March 19, 2026 • 10:24 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | DOWNSPOUTS | ANGLE 1
March 19, 2026 • 10:22 AM

BUILDING 1 | SOUTH | PORCH | ANGLE 1
⚑ Gap in perch ceiling
March 19, 2026 • 10:24 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | PORCH | ANGLE 2
March 19, 2026 • 10:24 AM

BUILDING 1 | SOUTH | PORCH | ANGLE 3
March 19, 2026 • 10:25 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | ROOFLINE | ANGLE 1
March 19, 2026 • 10:23 AM

BUILDING 1 | SOUTH | ROOFLINE | ANGLE 2
⚑ Missing fascia
March 19, 2026 • 10:23 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | ROOFLINE | ANGLE 3
March 19, 2026 • 10:24 AM

BUILDING 1 | SOUTH | SIDEWALK | ANGLE 1
March 19, 2026 • 10:19 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | SOUTH | SIDEWALK | ANGLE 2

Root causing raised sidewalk

March 19, 2026 • 10:19 AM

BUILDING 1 | SOUTH | WINDOW | ANGLE 1

March 19, 2026 • 10:24 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.

BUILDING 1 | NORTH | DOWNSPOUTS | ANGLE 1
March 19, 2026 • 10:26 AM

This visual record presents captured photos and notes at the documented times.
SCOUT provides the software used to organize and generate this report.